

GRAPHICAL SIMULATION SOFTWARE FOR
THE TOOL PATH WITHIN AN INTEGRATED
CAD/CAM/CNC ENVIRONMENT

by

SHANSHAN CHEN, B.E.

A THESIS

IN

INDUSTRIAL ENGINEERING


Submitted to the Graduate Faculty
of Texas Tech University in
Partial Fulfillment of
the Requirements for
the Degree of

MASTER OF SCIENCE

IN

INDUSTRIAL ENGINEERING

Approved



Accepted

December, 1995

AC
805
73
1195
No. 156

ACKNOWLEDGMENTS

AGN 761
TAC 5.15

cap. 2 I would like to give my uppermost appreciation to the chairman of my committee,

Dr. Hong-Chao Zhang, for his professional guidance throughout the course of this project. My thesis would not have been possible, but for the timely and invaluable directions given by Dr. Zhang. I am also extremely grateful for other members of my committee, Dr. Surya D. Liman and Dr. Atila Ertas, for their support and encouragement.

I want to express my gratitude to Mr. T. M. DeLaCruz, for his assistance in CNC machine operation, and Dr. Samuel Hang, for his precious suggestion. I want to thank Suresh Kalkavery for providing the initial model of the C program.

I wish to thank my parents for being the best teachers one could only dream of, every success that I achieved is because of them. Finally, I would like to thank my husband, Ken Li, for the love and courage he has given me.

TABLE OF CONTENTS

ACKNOWLEDGMENTS	ii
LIST OF FIGURES	vi
LIST OF TABLES	vii
CHAPTER	
1. INTRODUCTION	1
1.1 Computer-Aided Design (CAD)	1
1.2 Computer-Aided Manufacturing (CAM)	1
1.3 Computerized Numerical Control (CNC) Machining	3
1.3.1 The Architecture of CNC System	3
1.3.2 Machine Control Unit	4
1.3.3 NC Machine Motions	6
1.3.4 Cathode Ray Tube (CRT)	6
1.4 Integration of CAD/CAM for CNC Machining	7
1.4.1 Computer Aided Design and Manufacturing (CAD/CAM)	7
1.4.2 CAD/CAM in NC Machining	8
1.5 Research Objectives	8
2. TRIAC NC MILLING MACHINE	10
2.1 Basic NC Programming for TRIAC Milling Machine	10
2.1.1 The Coordinate System	10
2.1.2 Machine Axis Format	11
2.1.3 Absolute and Incremental Positioning	13
2.1.4 Tool Length Offsets	14
2.1.5 Preparatory Command (G-Code)	14
2.1.5.1 Repeat Function (G81)	17
2.1.5.2 Mirror Imaging Function (G10, G12)	18

2.1.5.3 Scale Function (G20)	20
2.1.6 Miscellaneous Command (M-Code)	21
2.1.7 Other Commands	22
2.1.8 Guidelines of NC Programming for TRIAC Milling Machine	22
2.1.9 Examples of NC Programming	24
2.2 Current Working Conditions of TRIAC Milling Machine	25
2.3 Advantages of Using Simulation Software for TRIAC Machine	27
 3. STRUCTURES OF THE SIMULATION SOFTWARE	 29
3.1 AutoCAD	30
3.1.1 Drawing Entity	31
3.1.2 Original Stock Drawing by Using AutoCAD Commands	32
3.1.3 Program Parameters File	35
3.2 AutoLISP Programming Language	38
3.2.1 AutoLISP Data Types	38
3.2.2 Function Defining and Loading	40
3.2.3 AutoLISP Functions	41
3.2.4 Stock Size Control	43
3.3 Script Command	44
3.3.1 Script File	45
3.3.2 DELAY Command Used in Script Facility	46
3.4 C Programming Language	47
3.4.1 The Structure of C Program	47
3.4.2 NC Programs Error Check in C Program	48
3.4.3 Calculations in C Program	50
3.4.3.1 The Calculation for the Geometry of Arcs	50
3.4.3.2 The Calculation for the Geometry of Mirror Image	51

3.4.3.3 The Calculation for the Geometry of Scaling	54
4. EXAMPLES OF TOOL PATH SIMULATION	55
5. CONCLUSIONS	69
5.1 Contributions of the Research	69
5.2 Suggestions for Future Research	70
REFERENCES	72
APPENDIX	
A. C PROGRAM “TRIAC.C”	73
B. AUTOCAD DRAWING OF THE ORIGINAL STOCK	95
C. THE SCRIPT FILE FOR FIGURE 5.1	97
D. THE SCRIPT FILE FOR FIGURE 5.2	104
E. THE SCRIPT FILE FOR FIGURE 5.3	110
F. USER MANUAL	127

LIST OF TABLES

2.1 G codes	15
2.2 NC code for the drilling example in Figure 2.4.	18
2.3 NC code for the milling example in Figure 2.5	20
2.4 NC code for the milling example in Figure 2.7	22
2.5 M codes	23
2.6 NC code for Figure 2.9	24
3.1 Drawing entities in AutoCAD	31
3.2 Five fields in acad.pgp file which defines external commands	36
3.3 Data types in AutoLISP language	38
3.4 Errors in NC program for TRIAC milling machine	49

LIST OF FIGURES

1.1 Arrangement of a NC machine tool	4
1.2 The basic elements of a CNC	4
1.3 Five major functional units of a computer numerical control system	5
2.1 Coordinate system of TRIAC NC machine	11
2.2 TRIAC machine axis format	12
2.3 An example of an incremental move	13
2.4 An example of tool movement parameters	14
2.5 An example of NC drilling (6mm depth)	17
2.6 An example of using mirror X and mirror Y function (3mm depth)	19
2.7 Scaling of a Contour	21
2.8 An example of using scale function (3mm depth)	21
2.9 An example part for milling (5mm depth)	25
2.10 TRIAC milling machine axis travel ranges	26
3.1 Structure of the NC simulation software	29
3.2 AutoLISP program for the stock size control	43
3.3 Structure of C program in simulation software	48
3.4 Start point, end point and center point of an arc	50
3.5 Milling a part by using Mirror X function	51
3.6 Milling a part by using Mirror Y function	52
3.7 Milling a part by using Mirror X and Y function	53
3.8 Milling a part by using Scaling function	54
4.1 Endmilling a simple part with lines and arcs, drilling operation included	56
4.2 Tool path simulation of the part in Figure 5.1	60
4.3 Endmilling text on a stock surface (2mm depth)	61
4.4 Tool path simulation of the part in Figure 5.2	64

4.5 Endmilling a part by using mirror function	65
4.6 Tool path simulation of the part in Figure 5.3	70
B.1 AutoCAD drawing of the original stock	96

CHAPTER 1

INTRODUCTION

1.1 Computer-Aided Design (CAD)

Computer-Aided Design (CAD) utilizes computers in the product development process to create the models of the products. Many properties of products, such as dimension, tolerance and structure, will be modeled by computational geometry and computer graphics. As a result, CAD provides tools by which enormous performance in productivity and efficiency may be realized.

CAD system consists of four basic aspects:

1. Hardware: the computers and related equipment;
2. Software: the CAD programming package running on the hardware, such as AutoCAD, or CADKEY;
3. Data: the data, such as geometry data is created and manipulated by the software;
4. Users' knowledge and skill.

The primary capability that CAD brings to the users is that of perfect scale drawing. The system allows the user to create accurate drawings in two dimensional, generate a complex three-dimensional surface, and to accurately model three-dimensional solids. It is the unique function of CAD system and the typical capability that sets it apart from other uses of computers. Designers and operators can also try a wide range of "what if" experiments with a design to improve quality and productivity.

The basic idea of using the Computer-Aided Design system is to:

1. improve quality and productivity,
2. cut the lead time,
3. reduce manufacturing cost.

1.2 Computer-Aided Manufacturing (CAM)

The number of Computer-Aided Manufacturing (CAM) applications is growing rapidly after the development of Computer-Aided Design (CAD). CAM relies on the CAD data, such as graphics of the design, and so on. Therefore, the relationship between computer aided design and manufacturing processes is closely tied. It is the relationship that provides the design of tooling, jigs, and fixtures and the generation of machine instructions for manufacturing and inspection.

The range of CAM applications vary greatly from highly automated tools which are predominantly graphics driven to pure language based tools where machine tool programmers use APT, and other programming languages to control the machines. (Bakerjian, 1989).

In addition, current technology provides the integration of both graphics and program languages in an application to maximize the productivity.

1.3 Computerized Numerical Control (CNC) Machining

Numerical Control (NC) machining refers to the manufacturing techniques with which machines, such as lathes and mills, are controlled by a series of coded instructions, rather than by the manual control of an operator. This numerical control system was first developed in the 1950s. In computer-aided manufacturing, operations are carried out by Computerized Numerical Control (CNC) machines. Today the terms NC and CNC are used interchangeably. The NC programs may be manually written by a NC programmer, or may be automatically generated by using the capabilities of CAD/CAM system. NC program implements the control algorithm for positioning the motion axes, providing the primary user-interface to the machine. After user-created NC programs are developed in the CAD system, the programs are downloaded into the control unit's memory by paper tape or floppy disk for execution in manufacturing of parts.

Modern CNC technology can not only control a single machining sequence on a particular workpiece but also accomplish multimachining operations. It achieves an

automatic tool change, displays the condition of the cutting tool, the time elapsed, and other useful data. The CNC technology improves: (Bakerjian, 1989).

- Planning, flexibility, and scheduling;
- Setup, lead, and processing time;
- Machine utilization;
- Tooling cost;
- Cutting tool standardization;
- Accuracy, efficiency, and productivity;
- Material flow and workpiece handling time;
- Interchangeability of work, tools, etc.
- Safety;
- Cost estimating.

Obviously, computer control technology has changed manufacturing technology more than any other single development (Bakerjian, 1989).

1.3.1 The Architecture of CNC System

The machine control unit of computer numerical control, known as MCU, allows the storage of local programs, the capabilities of reading and interpreting a stored program and the inclusion of some sophisticated operation functions, some command language, and the input and output facilities. The diagram for a CNC system is shown in Figure 1.1.




Figure 1.1 The arrangement of a NC machine tool (McMahon, 1993).

1.3.2 Machine Control Unit

The Machine Control Unit (MCU) is the microprocessor-based computer that control the operation of the NC machine. It is the heart of CNC system by which the information is exchanged from the host computer to the NC machine. The information is manipulated using hardware logic and software programs, and finally stored in the machine memory. The basic elements of a computer numerical control system are shown in Figure 1.2 NC programs are downloaded from the host computer to the MCU, or uploaded from the MCU to the computer. The MCU directs the NC machining operations according to NC codes, and received the information about tool change and machine position from the NC machine.




Figure 1.2. The basic elements of a CNC.

Five major functional units are in a machine control unit. Each unit performs a specific function, and all units together execute the programmed instructions. The Figure 1.3 shows the relationship among the five units. The solid lines with arrows represent the flow of the data. The dashed lines with arrows represent the flow of timing and control signals.




Figure 1.3. Five major functional units of a computer numerical control system. (Bakerjian, 1989)

There are three basic operating functions for a machine control unit:

1. MCU controls the normal running of the machine. This running may either be controlled by NC programming or be under direct manual control by the machine operator as a standard machine tool.
2. MCU provides useful machine status on the display screen. It displays the machine position and programmed goal position, spindle speed, feed rate, current cutting tool, alarm, and other information. The operator can verify correct running of the machine and prevent damage by checking the machine status.

MCU can manipulate the stored NC programs. The control unit can download the NC programs from the CAD system from a linked computer, allow operator to edit programs by using the keyboard on the MCU. The ability of uploading programs back to the CAD system is also provided. In distributed numerical control (DNC) where NC programs

remain on a computer and are electronically transmitted to the MCU, it can direct the machine by using a communication port (RS232) rather than from stored programs.

1.3.3 NC Machine Motions

It is known that there are three major NC machine motions.

1. Point-to-point is the simplest type of the machine motions. It moves a tool from one specified position to another while some operations are carried out. The actual path between these two positions is not too significant to be considered. For instance, during the drilling operation, only point-to-point control may be required.
2. Straight-cut is a kind of the machine motions which moves the cutting tool paralleled to one of the machine axis, such as X axis.
3. Contouring is the most complex machine motion with the capability of point-to-point and straight-cut control. It also provides simultaneous precise control of more than one machine axis. For example, the linear interpolation (movements between positions by straight lines) and the circular interpolation (movements as arcs or circles), are required contouring control.

The speed of machine motion is controlled by the feed rate (F code) in NC program. Some additional motions are described as the control of the operation spindle speed, the coolant supply, the tool changes, and so on.

1.3.4 Cathode Ray Tube (CRT)

The latest CNCs are using a visual display of NC programming and other parameters by the cathode ray tube (CRT). It is very similar to a TV screen. The upper right part of Figure 1.1 is a CRT. The most typical feature of CRT is that the screen not only displays the full operational and parametric data, the running program, but also generates graphics. Moreover, CRT also displays some error message to help perform high quality products.

1.4 Integration of CAD/CAM for CNC Machining

1.4.1 Computer-Aided Design and Manufacturing (CAD/CAM)

Pasemann (1986) pointed out that CAD/CAM integration means first of all well functioning interfaces between these systems providing internal or external communication of product data. It is recognized that the different steps in the development of a manufactured product are interrelated and can be accomplished more effectively and efficiently with computers. CAD/CAM system combines the precision of electronic graphics and the mathematical processing power of the digital computer to provide many diverse capabilities. The CAD/CAM applications refer from engineering analyses to manufacturing controls. Typically, the connection that CAD/CAM provides between geometric models and the number crunching power of computers allows it to provide vast productivity improvements in numerical control (NC) system. Overall, CAD/CAM integration is a key to the manufacturing which improves the productivity, efficiency, and profitability in current industry.

Several functions of CAD/CAM systems are described below:

1. A CAD/CAM system can automatically generate production information based on the geometric model contained in the CAD part. This information can be used in many ways during the manufacturing process. For instance, it may be formatted numerical control information which is used in a variety of ways by directing it to different numerically controlled machines or systems, or it may be milling information to direct a milling machine to mill a surface as described in the CAD part.
2. A digital computer of the CAD/CAM system provides the capability for writing and using a variety of computer programs for calculations or for processing information. The capabilities of this digital computer are not specific to CAD/CAM, but can be developed on any computer.
3. The communications capabilities which provide a method for exchanging information with other computers via the established telecommunications networks (such as

RS232) are also used in CAD/CAM system. This information may be numerical control information, CAD drawing information, or any other type of information.

All-sidedly, the integration of CAD/CAM is not only based on the physical part of product being produced, but also on the data that define and direct each step in the manufacturing process.

1.4.2 CAD/CAM in CNC Machining

After a NC programmer finishes programming, and before an operator begins to manufacture the part, it is very helpful for them to watch a graphic representation of the path superimposed on the part geometry. A CAD/CAM system can be developed to generate automatically the optimal cutter path, to move from one machining feature to the next.

Current research focuses on the NC tool path simulation with the ability to display the cutter path superimposed on the part geometry. CAD system displays cutter location on a color screen rather than in black and white screen. Additionally, the CAD/CAM system suggests that the geometry as a shaded image is in one set of color, and then the tool path is in a contrasting color. Cutting paths are as solid lines and rapid movements in air are seen as dotted lines. Therefore, CAD/CAM system makes CNC manufacturing process simulation more powerful and clear than any other simulations.

1.5 Research Objectives

TRIAC vertical NC milling machine is used to practice the part design, NC programming and CNC machining by the students in Industrial Engineering Department at Texas Tech University. It was made in England in 1985. Since it has been used for education for about ten years, there are several problems occurred during recent operation.

1. The alpha numeric keyboard used to allow full manual data input. But currently, some of the keys are stick up and can not be used to enter data into the NC machine, such as

key G81 and Mirror X. RS-232 communication port is used to transfer the NC program from the host computer to TRIAC milling machine.

2. MCU lost its control about some of the functions, such as tool offset function.
3. The alarm for error checking in TRIAC machine is incomplete because of loss functions.
4. The tool path simulation on TRIAC CRT may be generated without checking the error completely. Therefore, the tool path simulation is failure, too.

Because of the reasons mentioned above, it is dangerous to download the NC code and run the machine without checking the program for errors. Currently, the approach to Computer Numerical Control programming is rapidly developed. A graphics based tool path simulation system is necessary to enable the utilization of graphics for the NC programming and extend the NC operating capability by using simulation. The objectives of this research is going to build up a software interface for TRIAC NC machine to verify the NC programs' syntax, semantics, and generate the NC tool path in AutoCAD environment. This software package is the bridge exchanged data between CAD geometry data and NC codes. CAD-interfaces are the most important topic in the realm of CAD/CAM integration.

The graphics-based simulation system developed includes a CAD module, an error control and tool path simulation software, a CNC machine, and a communication package. The simulation software is written for the MS-DOS Operating System. In this integrated system, the blank drawing and the tool path are prepared in the CAD module using different line types and colors. The procedure in graphical simulation is that the simulation software reads the NC code, checks the program syntax error, converts the NC code into AutoCAD script file and generates the tool path in AutoCAD environment.

Although currently there are many software packages that have been developed to help assist the NC programmers. This graphical simulation software developed here is customized for the use of TRIAC milling machines. It assists to produce high quality, precision products more efficiently, and fulfills education requirements.

CHAPTER 2

TRIAC NC MILLING MACHINE

The TRIAC vertical milling machine is located in the manufacturing lab of Industrial Engineering Department at Texas Tech University used by the students to perform course projects. It is a computer based programmable numerical control unit, which utilizes the advances in microprocessor technology to control a 3-axis activated stepper motors. TRIAC's NC programming format is according to the International Standard incorporating G and M codes.

Programming facilities include integral spindle control, circular, repeat, fixed or floating datum, inch or metric and absolute or incremental programming, dwells, program scaling, mirror imaging, tool diameter and length compensation.

The total memory of the control unit is 750 blocks.

2.1 Basic NC Programming for TRIAC Milling Machine

This section is to be used as a introduction to the NC programming, especial for the TRIAC milling machine.

2.1.1 The Coordinate System

The diagram below shows a top view of the grid as it would appear on the machine tool. This view shows the X and Y axes as the operator faces the machine tool. Tool moves away to the right of zero is positive increase; away to the left of zero is negative increase. Tool moves away from operator is positive increase along Y direction; and moves close to operator causing a negative increase.




Figure 2.1. Coordinate system of TRIAC NC machine

The work zero in the Z-axis is usually set at the top of the part surface, this will be entered in the tool length offset as a negative value. Tool moves above the part surface is positive increase, otherwise, negative increase.

2.1.2 Machine Axis Format

TRIAC machine is a three axis mill. The illustration shows the positive and negative, indicating the direction of the tool movement. It is very important concept to understand that all motions programmed are the movements of the tool, not the movements of machine table.

Originally starting TRIAC from a cold start, there is no operation until machine has been datumed. Each axis is driven to a limit switch, Z, Y, and X axis, respectively. Each limit switch position is maximum positive motion for that axis. The machine initially being the bottom left hand corner of the table for X and Y axes.

Figure 2.2 shows the machine axis format.






Figure 2.2. TRIAC machine axis format

X-	Left forward movement of tool
X+	Right forward movement of tool
Y-	Tool moves away from the operator
Y+	Tool moves towards the operator
Z-	Downward movement of the tool
Z+	Upward movement of the tool

2.1.3 Absolute and Incremental Positioning

In absolute positioning, all coordinate points are given with regard to their relationship to the origin, a fixed zero point, or considered as part zero. This is the most common type of positioning.

Incremental positioning concerns itself with distance and direction. A new coordinate is entered in terms of its relationship to the previous position, and not from a fixed zero or origin. In other words, after a block of information has been executed, the position that the tool is now at is the new zero point for the next move to be made. An example of the use of the incremental system is in Figure 2.3. Note that to move from X4.0 to X2.0 on the scale, an incremental move of X-2.0 was made, even though the move still places the tool on the plus side of the scale. Therefore the move was determined from the last point, with no regard for the zero position. The + and - signs are used in terms of direction, and not in regard to the position of zero.




Figure 2.3. An example of an incremental move.

The types of coordinate position system are described in NC program as follow:

- G90 Absolute dimensional positions.
- G91 Incremental dimensional positions.

2.1.4 Tool Length Offsets

Tool length offsets are defined as a measured distance from the machine fixed zero to a plane at which the part is programmed, usually the top of the workpiece.

To program the Z axis, the location of the tip of the tool is be considered every time. At the setup period, the tool is moved until its tip is reached the top of the workpiece. The machine control automatically adds or subtracts the tool length and places the tool point at the desired location.

Figure 2.4 provides an example of tool offset. If Z offset for the tool is 60mm, then the parameters of movement for that tool are:

$$Z + 175 \sim Z - 60 = 235 \text{ mm}$$




Figure 2.4. An example of tool movement parameters

2.1.5 Preparatory Command (G-code)

NC machines receive instructions as a sequence of blocks which contain different commands to control machine operations and set parameters, dimension and speed. The preparatory function (G-code) prepares the machine control unit with an operation, especially involving a cutter movement.)

Table 2.1. G Codes

G00 or G0	<p>Rapid Motion Positioning. All motions rapid traverse in linear mode.</p> <p>X Optional X-axis motion command</p> <p>Y Optional Y-axis motion command</p> <p>Z Optional Z-axis motion command</p>
G01 or G1	<p>Linear Interpolation Motion. It is the mode of program to move the tool in a straight line that is parallel to an axis or at some angle to an axis. Depressing X, Y or Z key will default to G01 linear mode.</p> <p>F Feed rate in inches (mm) per minute</p> <p>X Optional X-axis motion command</p> <p>Y Optional Y-axis motion command</p> <p>Z Optional Z-axis motion command</p>
G02 or G2	<p>Clockwise Circular Interpolation Motion. It is to be used when the tool is to follow the path of a circular arc while moving in a clockwise direction for X and Y axis.</p> <p>F Feed rate in inches (mm) per minute</p> <p>X Optional X-axis motion command</p> <p>Y Optional Y-axis motion command</p> <p>Z Optional Z-axis motion command</p> <p>XC Circle center for X-axis</p> <p>YC Circle center for Y-axis</p>

Table 2.1. Continued.

G03 or G3	<p>Counterclockwise Circular Interpolation Motion. It is to be used when the tool is to follow the path of a circular arc while moving in a counter-clockwise direction for X and Y axis.</p> <p>F Feed rate in inches (mm) per minute</p> <p>X Optional X-axis motion command</p> <p>Y Optional Y-axis motion command</p> <p>Z Optional Z-axis motion command</p> <p>XC Circle center for X-axis</p> <p>YC Circle center for Y-axis</p>
G04 or G4	Dwell. No Movement will occur while a timed dwell is performed.
G10	Mirror X. It is for changing over the position and negative direction of the X axis.
G12	Mirror Y. It is for changing over the positive and negative direction of the Y axis.
G13	Cancel Mirror Y. This function cancels Y mirror function.
G20	Program Scale. This function allows a program scale 0.01% to 650% to be entered into the program.
G54	Program Offset. This function allows an incremental offset within the program.
G70	Imperial Units. This function selects imperial units for the program
G71	Metric Units. This function selects metric units for the program.
G81	Repeat Function. This function selects a repeat loop which will allow a programmed sequence to be repeated with specified offsets.
G90	Absolute Input. This function selects absolute format.
G91	Incremental Input. This function selects incremental mode, and allows incremental input with absolute display.

2.1.5.1 Repeat Function (G81)

The repeat facility enables specified sections of a programmed sequence to be repeated. It is only permitted within a programmed sequence. The data required to specify a repeat is:

1. The start block number to be repeated, this must be linear block with all axes defined. X, Y and Z dimension within the start block.
2. The end block number to be repeated.
3. The number of repeats required.
4. Feed. Entering a feed into the repeat loop will change all feeds programmed within the loop to the new feedrate. Omitting a feedrate value will leave all feeds as initially programmed.

When each repeat is programmed the control checks all the dimensions being repeated, adding the programmed offset to the number of repeats to ensure that the machine limits are not exceeded. The example in Figure 2.5 and Table 2.1 show how to use the repeat function G81.




Figure 2.5. An example of NC drilling (6mm depth)

Table 2.2. NC code for the drilling example in Figure 2.4.

<u>N</u>	<u>G</u>	<u>M</u>	<u>From</u>	<u>To</u>	<u>REP</u>	<u>X</u>	<u>Y</u>	<u>Z</u>	<u>F</u>
01		03							
02	00							3	
03	00					10	10		
04	01							-6	100
05	00							3	
06	81		3	5	3	+10			
07	81		3	6	3		+10		
08	00					0	0		
09		05							
10		02							

2.1.5.2 Mirror Imaging Function (G10, G12)

The mirror imaging function provides the cutter transformation ability to mill a contour or drill holes by inverse of one or more axes in another plane. Such "mirroring" of a coordinate axis permits contour machining in the following relationship (Smith, 1993):

1. with the same dimensions;
2. at the same distance from the other axes;
3. on the other side of the "mirror axis", but as a "mirror-image".

Mirror function changes:

1. the sign of the coordinates of the mirrored axis. For example, when G10 mirror X is used, the point (10, 10) is changed to be (-10, 10), and the sign of the coordinates of the Y axis is not changed.
2. the direction of rotation. When circular interpolation (G02, G03) is occurred in the NC program, the mirror function changes the direction of rotation from clockwise to counter-clockwise, or vice versa.

The mirror function is always in relation to the mirror axis, such as X axis (when using G10 Mirror X), according to which the contours can be mirrored and machined in the exact position. In order to achieve this axis symmetry, a zero position of the coordinate system needs to be set before any mirror function being activated in the program.

The following Figure 2.6 demonstrates using mirror function to repeat milling a triangle in negative quadrant.




Figure 2.6. An example of using mirror X and Y function (3mm depth)

Table 2.3. NC code for the milling example in Figure 2.5.

<u>N</u>	<u>G</u>	<u>M</u>	<u>From</u>	<u>To</u>	<u>REP</u>	<u>X</u>	<u>Y</u>	<u>Z</u>	<u>F</u>
01	00					0	0	3	
02		03							
03	00					10	10	3	
04	01							-3	75
05	01					50	10		75
06	01					60	40		
07	01					10	10		
08	00							3	
09	00					0	0		
10	10								
11	12								
12	81		3	9	1				
13		05							
14	11								
15	13								
16	00					-80	0		
17		02							

2.1.5.3 Scale Function (G20)

Scale function (G20) is an other very helpful cutter transformation function, which enlarges or reduces the milling contours. A typical schematic of the "scaling" of a contour is shown in the following Figure 2.7, demonstrating and clarifying the range of size variation when using scaling factors. The scaling factor determines the enlargement or reduction of contours, and automatically calculates the new dimensions and coordinates. For instance, G20 50, means to reduce the contours 50% with the scaling factor 50.




Figure 2.7. Scaling of a Contour

The following example is using scaling function to milling a contour in different sizes.




Figure 2.8. An example of using scale function (3mm depth)

Table 2.4. NC code for milling a part in an example in Figure 2.7.

<u>N</u>	<u>G</u>	<u>Scale</u>	<u>M</u>	<u>From</u>	<u>To</u>	<u>REP</u>	<u>X</u>	<u>Y</u>	<u>Z</u>	<u>F</u>
01			03							
02	00						0	0	3	
03	01								-3	75
04	01						38	0		75
05	01						65	75		
06	01						0	120		
07	00								3	
08	00						0	0		
09	10									
10	81			3	7	1	0	0		
11	11									
12	20	83.33								
13	81			3	11	1	0	0		
14	20	50								
15	81			3	11	1	0	0		
16		02								

2.1.6 Miscellaneous Command (M-code)

Miscellaneous functions (M-code) are provided to designate a particular mode of operation, typically to switch a machine function on or off, such as coolant on or off and spindle on or off.\

Table 2.5. M Code

M02 or M2	Program End. This function will end the program. Once reaching this point the spindle will stop and the tool will retract to its home position.
M03 or M3	Spindle Forward. The M03 will start the spindle rotation in clockwise direction. The desired spindle speed (RPM) value can be entered.
M04 or M4	Spindle Reverse. The M04 function starts the spindle rotation in counter-clockwise direction.
M05	Spindle Stop.
M06	Change Tool.

2.1.7 Other Commands

There are other commands classified as follow:

- Sequence number (N-code) is used to identify the number for the block in ascending numerical order.
- Feed functions (F-code) are used to set the cutter feed rates to be applied.
- Speed functions(S-code) are used to specify the spindle speed.
- Tool functions (T-code) are used to specify the cutter to be used.
- End of block character (L) is used in TRIAC NC machine to signify the end of the block.
- Coordinate characters (X, Y, Z codes) are used to specify the geometric data of the coordinate system.

2.1.8 Guidelines for NC Programming for TRIAC Milling Machine

There are a few guidelines which govern the use of all codes for programming the TRIAC controls.

1. One G Code is permitted per block.
2. One M Code is permitted per block.
3. M and G codes cannot be entered on the same line.
4. There are modal G codes which, once established, remain effective until replaced with another code from the same group.
5. In order to perform the necessary machine operations, there are several information need to be specified, such as tool selection (T code), spindle speed (S code) and feedrate (F code).
6. The workpiece dimension, the tool travel and the axis of the slideways should be considered before programming.
7. There are non-modal G codes which, once called, are effective only in the calling block, and are immediately forgotten by the control.
8. The M code will be the last item of code to be performed, regardless of where it is located in the line.

2.1.9 An Example of NC Programming

In the following example of NC programming, Repeat G81, Mirror Image G10, G12, and Scale Function G20 are utilized to mill three quarter circles. An absolute NC code for Figure 2.9 is show in Table 2.6:

Table 2.6. NC code for Figure 2.9.

N1 M3 L	; Spindle Forward
N2 G00 X10 Y0 Z10 L	; Move to point (10,0,10)
N3 G01 Z-5 F50 L	; Mill 5mm into the part
N4 G01 X30 L	; Mill the part to the point (30,0)
N5 G03 X10 Y20 XC10 YC0 L	; Mill an arc to point (10,20) with center (10,0)
N6 G01 Y0 L	; Move to the point (10,0)
N7 G01 Z10 L	; Retract the tool 10mm above the part
N8 G00 X0 Y0 L	; Move the tool to the point (0,0)
N9 G10 L	; Mirror X function
N10 G81 R2 E8 N1 X0 Y0 L	; Repeat program loop from N2 to N8 once
N11 G11 L	; Mirror X function cancel
N12 G20 150 L	; Scale 150%
N13 G81 R2 E8 N1 X10 Y0 L	; Repeat program loop from N2 to N8 Once
N14 M05 L	; Spindle stop




Figure 2.9. A sample part for milling (5mm depth).

2.2 Current Working Conditions of TRIAC Milling Machine

TRIAC milling machine's longitudinal travel (X) is 290mm(11.5"); cross travel (Y) is 170mm (6.5"); vertical travel (Z) is 235mm(9.5"). The following Figure 2.10 shows the TRIAC machine axis travel ranges. When machine X and machine Y are equal to zero, the tool head is at a point near the front left hand corner of the table. When machine Z is equal to zero, the tool is at maximum distance from the top surface of the stock.




Figure 2.10. TRIAC milling machine axis travel ranges

TRIAC uses RS232C serial link to download NC programs from the computer to the machine control unit, or download the programs from the machine to the computer.

Since TRIAC is an obsolete NC milling machine, there exist some limitations of NC programming by current working conditions of TRIAC machine:

1. The machine axis travel range of TRIAC machine is $X=290\text{mm}$, $Y=170\text{mm}$ and $Z=235\text{mm}$. This should be considered before programming.
2. Some of the function keys are out of control. As a result, it is better to use data transfer from computer to NC machine than to use manual edit and manipulation.
3. Several functions in the program are useless, such as M20, M21, G40, G41, G42, G70, G71.
4. M code and G code can not be in the same block.

5. No more than two M-code or two G-code can be in the same block.
6. Blank lines are not accepted.
7. Lower case letters can not be accepted.
8. Speed command (S-code) and other NC code can not be in the same block.
9. Only one feed rate command (F-code) can be specified in a block, and need to put at the end of the block.
10. Every block must end with the letter "L".
11. The scale range is 0.01% to 650%.
12. The arc should begin and end in the range of one quadrant. In other word, a circle need to be programmed by using the combination of four arcs.

2.3 Advantages of Using Simulation Software for TRIAC Machine

Manual programming demands a NC programmer to determine the manufacture process and the machine operation directly without using the aid of computers. However, much detailed calculation is required to realized the cutter path. It causes potential errors, such as incorrect calculation and the risk of making mistakes in entering data. The simulation software is used for error detection, which can save valuable production time, especially for the TRIAC NC milling machine. The advantages of using graphical simulation software for TRIAC machine are:

- The tool path graphics can be simulated with several available views. From those views, the programmers or the operators can check the tool path step by step.
- The graphical simulation software can generate an original stock drawing with three alternative views in AutoCAD.
- Every block in NC program is checked by this simulation to keep it correct when transfer to the TRIAC milling machine.
- There are error message to help the programmers make changes of their NC programs.
- The rapid tool movement and cutting movement are demonstrated in different colors.

- The simulation reduces the time for editing NC programs. Because of different key board and key board position, it is much faster to key in on the computer than key in on the TRIAC milling machine.

CHAPTER 3

THE STRUCTURES OF THE SIMULATION SOFTWARE

The following flow chart shows the structure of the tool path simulation software. The first part of the software is using C language program to verify the NC codes and transfer them into AutoCAD script file. The second part of the software is using AutoCAD basic commands and AutoLISP language program to generate a graphic with stock size in three different views. Finally, the two parts combine to create a NC tool path in AutoCAD.




Figure 3.1. Structure of the NC simulation software.

3.1 AutoCAD

AutoCAD is a general purpose Computer-Aided Design (CAD) program for preparing two-dimensional drawings and three-dimensional models. AutoCAD is used in fields as diverse as Architecture, Engineering, Geographical Information Systems, Desktop Publishing, Electrical Design, and Process Industry Design. It provides a full range of drafting tools that let user create accurate and realistic images that meet the ANSI standards for drafting (Autodesk, Inc.1992).

From the AutoCAD Tutorial (1992), it states that AutoCAD is a multi-purpose software package that can be used in many different applications, disciplines, and environments. It uses support files to store menu definitions, load AutoLISP programs, define linetypes, define hatch patterns, and so on. Many of the support files in AutoCAD are ASCII files and can be edited with a simple text editor. These files are not integral to AutoCAD, and can be customized so that AutoCAD works the way the user want it to.

The graphical tool path simulation is based on AutoCAD drafting commands. The following commands are used to modify this simulation software:

- SCRIPT command,
- DELAY command.

The features covered in the simulation software are list as follows:

- Modifying the acad.pgp file,
- Adding an external command to the acad.pgp file.

At first, the AutoCAD basic commands are used to create a plan view. A stock is shown with a plan view in the upper-left viewport, a side view in the lower viewport, and an isometric view in the right viewport. Viewport let user work with different views of the same drawing. The second, AutoLISP programming language is used to control the contour and the size of the stock. The third, script file provides a continuously running displays for the tool path demonstration.

3.1.1 Drawing Entity

AutoCAD creates drawing by using drawing entities, such as Lines, Arcs, Polylines and Circles. An entity is a predefined element that a drawing is modified by the means of commands. The following table describes the drawing entity types which provided by AutoCAD.

Table 3.1. Drawing entities in AutoCAD (Autodesk, Inc.,1992)

<i>Entity type</i>	<i>Description</i>
Lines	Drawn with various dot-dash linetypes. When drawing a line segment, provide either 2D (x, y) or 3D (x, y, z) coordinates.
Arcs and Circles	Drawn with various dot-dash linetypes. Several methods are provided for drawing arcs and circles.
Points	Appear as dots, squares, circles, Xs, or any combination of these. Point entities can be located by using either 2D or 3D coordinates.
Text	Appears in various fonts with any size and orientation.
Traces	Two-dimensional, solid-filled lines of any width user specify.
Solide	Two-dimensional, solid-filled triangular, or quadrilateral objects.
Shapes	Small objects which can define outside AutoCAD and place in the drawing with a specified scale and rotation.
Blocks	Compound entities formed from groups of other entities (or blocks).
Attributes	Attach constant or variable text information to each instance of a Block.
Dimensions	Compound entities similar to Blocks, containing all lines, arcs, arrows, and text constituting a dimensioning annotation.
PolyLines	2D connected line and arc segments, with optional dot-dash linetypes, width, and taper. Commands are provided to construct ellipses, regular polygons, filled circles, and doughnuts using polylines.
3D Polylines	3D objects composed of straight-line segments (but no arcs, width, taper, or quadrilateral plane sections.

Table 3.1. Continued.

3D Faces	3D triangular or quadrilateral plane sections.
3D Meshes	3D polygon meshes of rectangular topology. Commands are provided to construct ruled surfaces, surfaces of revolution, and tabulated cylinders using 3D Meshes.
Polyface Meshes	Polygon meshes of arbitrary topology. Defining a polyface mesh allows user to avoid having to create many unrelated 3D face with coincident vertices.
Viewports	Rectangular areas in paper space that contain a view of model space.

3.1.2 Original Stock Drawing by Using AutoCAD Basic Commands

The following steps are used to perform the original stock drawing in AutoCAD. This AutoCAD drawing is in Appendix B.

Enter AutoCAD R12. C:\> *acadr12*.

Command: *new*

Command: *Units* (1)

Enter choice: **2** (Decimal)

Number of digits to right of decimal point (0 to 8) <4>: **4**

Systems of angle measure, enter choice, 1 to 5 <1>: **1** (Decimal degrees)

Number of fractional places for display of angles (0 to 8)<0>: **0**

Enter direction for angle 0 <0>: **0** (East 3 o'clock = 0)

Do you want angles measured clockwise? <N>: **Y**

Command: *limits* (2)

Reset Model space limits:

ON/OFF/<Lower left corner> < 0.0000,0.0000>: **Enter**

Upper right corner <12.0000, 9.0000>: **29.0000, 17.0000**

Command: *graphscr* (3)

Command: *ddrmodes* (4)

Snap: *on* Grid : *on*

X Spacing: *0.5000*

Y Spacing: *0.5000*

Command: *zoom* (5)

All/Center/Dynamic/Extents/Left/Previous/Vmax/Window/<Scale(X/XP)>:A

Command: *zoom*

All/Center/Dynamic/Extents/Left/Previous/Vmax/Window/<Scale(X/XP)>:0.9

Command: *elev* (6)

New current elevation <0.0000>: *0.0000*

New current thickness <0.0000>: **2.0000**

Command: *line*

From point: *0.0000, 0.0000*

To point : **20.0000, 0.0000**

To point: **20.0000, 15.0000**

To point : ***0.0000, 15.0000***

To point : ***0.0000, 0.0000***

Command: *tilemode* (7)

New value for TILEMODE <1>: 0

Entering paper space. Use MVIEW to insert Model space viewports.

Regenerating drawing.

Command: *mview* (8)

ON/OFF/Hideplot/Fit/2/3/4/Restore/<First Point>: 3

Horizontal/Vertical/Above/Below/Left/Right: *right*

Fit/<First Point>: **0.5000,0.5000**

Second point: ***12.0000, 8.5000***

Command: *Mspace* (9)

Click the upper-left viewport.

Command: *vpoint* (10)

Rotate/<View point><0.0000,0.0000,1.0000>: *0.0000, 1.0000, 0.0000*

Regenerating drawing.

Click the right side of the viewport.

Command: *vpoint*

Rotate/<View point><0.0000,0.0000,1.0000>: *1.0000, 1.0000, 1.0000*

Regenerating drawing.

1. Units. The distance between two coordinate points is measured in units. There are several kinds of units in AutoCAD, such as scientific, decimal, engineering, architectural, and fractional.
2. Limits. AutoCAD drawings are always in a rectangular area. The drawing limits specify the potential size of the rectangle, expressed in X, Y drawing coordinates.
3. Graphscr. The command return AutoCAD to graphic screen.
4. DDEMODES. This command set the grid and snap on or off. The grid displays a reference grid of points with desired spacing. Points entered in AutoCAD drawing can be locked into alignment with an imaginary rectangular grid by the snap command.
5. Zoom. Zoom command increases or decrease the apparent size of the drawing in the current viewpoint, and the actual size of the drawing remains constant.
6. Elevation and thickness. The elevation of a drawing is the Z value of the XY plane on which its base is drawn. The thickness of a drawing is the length that object is to be extruded above its elevation.
7. Tilemode. Tilemode is a system variable which controls access to paper space.
 - Tilemode On (1) = Enables uses VPORTS.
 - Tilemode Off (0) = Enables paper space and Viewport entities (uses MVIEW).AutoCAD clears the graphics screen to let user create one or more viewports.
8. MVIEW. MVIEW operates in paper space to create new viewports, turn viewport display on or off, and remove hidden lines.

9. MSPACE. MSPACE change paper space to model space.
10. Vpoint. Vpoint set the viewing point for the current drawing. AutoCAD regenerates the drawing, and displays the drawing as seen it from the point in model space.
 - View point (0,0,1) A top view.
 - View point (1,0,0) A front view.
 - View point (1,0,0) A right view.
 - View point (1,1,1) A top, right, front view.

3.1.3 Program Parameters File

The *acad.pgp* is the AutoCAD program parameters file, which stores command definitions used by AutoCAD. This file is divided into two sections: the first section defines external commands, while the second section defines command aliases. In addition, this file can contain comments, which must be preceded by a semicolon (;). (Autodesk, Inc.1992). This file can be modified with any text editor. When AutoCAD starts, it searches the library file path and reads the first *acad.pgp* file it finds, ignoring other files with the same name. AutoCAD reinitializes the *acad.pgp* file each time when open a new or existing drawing.

Other programs might be executed in AutoCAD in this manner include:

- Internal DOS command, such as *type*;
- Other DOS or UNIX utilities, such as *diskcopy* or *grep*;
- Text editors and word processors;
- Database managers;
- Spreadsheets;
- Communications programs;
- User- supplied programs.

In order to run another program from within AutoCAD, the name of the program and other related details must be known by AutoCAD. This information need to be supplied in the external commands section of *acad.pgp*.

When the external commands are defined in *acad.pgp*, each line describes a program that can be executed from within AutoCAD. The new commands are considered to be a list of custom AutoCAD commands.

Each line in *acad.pgp* that defines an external command has five fields, delimited by commas.(Autodesk, Inc. 1992). The five fields in *acad.pgp* file are described in Table 3.2.

Table 3.2. Five fields in *acad.pgp* file which defines external commands.
(Autodesk, Inc., 1992)

Command name	The AutoCAD external command to be added. This is what will be entered at the Command: prompt. It must not be an internal AutoCAD command or it will be ignored .
File command	This constant string is sent to the operating system for execution when enter the command name. It can be any valid command to be executed at operating system's command prompt. The string might include switches, parameters, and so on.
Memory reserve	This field serves to maintain compatibility with previous versions of AutoCAD. Although AutoCAD does not use the value in this field, a number (typically 0) must be present.
Prompt	This field, if supplied, specifies a prompt to be displayed to the user. The response to this prompt is appended to the constant command string supplied by the file command field or specifies a block name.
Return code	This is an optional bit-coded parameter. These integer values can be added together in any combination to achieve the result user wants. The value are defined as follows: 0 Return to text screen 1 Load DXB file 2 Construct block from DXB file 4 Return to previous screen mode

Here the *acad.pgp* file is used to define an external command -- **TRIAC**. AutoCAD ignores blank lines and all text to the right of a semicolon. The following is an example of an *acad.pgp* external commands section, the external command “TRIAC” is added:

```
.....  
DEL, DEL,          0, File to delete: ,4  
DIR, DIR,          0, File specification: ,0  
EDIT, EDLIN,0, File to edit: ,4  
SH, ,              0, *OS Command: ,4  
SHELL,,            0,*OS Command: ,4  
TYPE, TYPE,        0, File to list:, 0  
TRIAC, TRIAC,      0,      ,4  
.....
```

The first TRIAC is the AutoCAD external command name. The second TRIAC is the file command. It is sent to the operating system for execution when the command name is entered. The number ‘0’ presents a field which serves to maintain compatibility with previous versions of AutoCAD. The next field is called prompt field. It specifies a prompt to be displayed after the command is used. TRIAC command does not need prompt. Hence, keep the field empty. After the command is executed, the number ‘4’ called return code is used to return to previous screen mode. The defined external commands are for interactive use only.

3.2 AutoLISP Programming Language

One of the most powerful capabilities for extending AutoCAD is AutoLISP. AutoLISP, an integral part of AutoCAD, is a specialized implementation of the LISP programming language. It is used to create new AutoCAD commands and automate

repetitive tasks. AutoLISP lets users write macro programs and functions in a powerful high-level language suited to graphics application. (Autodesk, Inc.1992).

3.2.1 AutoLISP Data Types

There are eight major data types in AutoLISP programming language (Table 3.3).

Table 3.3. Data types in AutoLISP language

<u>Data Type</u>	<u>Function</u>	<u>Example</u>
Symbols.	Symbols are used to store values.	The following example shows the setq function to set the symbol p1 to the point value (4.0,5.0): (setq p1 '(4.0 5.0))
Lists	Lists stores numbers; related values are in one symbol.	For instance, (3 4) indicates that a 2D point. The first value is the X coordinate and the second value is the Y coordinate. (3 7 5) expresses a 3D points. The first value is the X coordinate, the second value is the Y coordinate, and the third value is the Z coordinate.
Strings	Strings have unlimited length.	
Integers	Integers are values entered without a decimal point.	

Table 3.3 Continued.

Real numbers	Real numbers are numbers entered with a decimal point.	
File descriptors	When an AutoLISP function needs to access a file, its label must be referenced. At this moment, file descriptors are alphanumeric labels assigned to those files.	<p>The example below opens a file called <i>temp.lsp</i>, allowing it accessible to other functions for writing, and assigns the value of file descriptor to the symbol <i>data</i>:</p> <pre>(setq data (open "temp.lsp" "w")) -- return <File: #34662></pre>
AutoCAD entity names	An entity name is a pointer assigned to entities in a drawing.	
AutoCAD selection sets	Selection sets are groups of entities which can be added or removed.	<p>For instance: (setq su (ssget "P"))</p> <pre>-- return <Selection set: 1></pre> <p>This example assigns the selection set -- the previously selected objects to the symbol <i>su</i>.</p>

AutoLISP names variables with an alphabetic character as the first character.

There are four kinds of variables:

1. integer,
2. real,
3. point,
4. string.

The AutoLISP **setq** function is used to assign values to variables. The format is as below:

(*setq variable value*)

3.2.2 Function Defining and Loading

Every AutoLISP expressions should be preceded by an opening bracket, and should have a corresponding closing one. Such as:

(*function-name [arguments] ..*)

All of the AutoLISP functions can directly access to AutoCAD by enter the function after “**Command:**”. These functions are currently loaded, and when quit the drawing, they will not be saved.

The AutoLISP **load** function is provided to save function definitions in files with an extension of *.lsp* and load them in every drawing. During the file loading, all expressions are evaluated. The **defun** function is used to store groups of functions in the AutoCAD memory for later execution. The unique character of AutoLISP is that it can add new commands to AutoCAD. The C: *name* function make this character realizable. For example, the following AutoLISP file is used to draw a square on AutoCAD by using SQUARE command.

```
(defun C: SQUARE ( / p1 p2 p3 p4 len)
  (setq p1 (getpoint "Enter the lower left corner:"))
  (setq len (getdist p1 "Enter the square length:"))
  (setq p2 ( polar p1 0.0 len)
  (setq p3 ( polar p2 (/ pi 2) len))
  (setq p4 ( polar p3 pi len))
  (command "pline" p1 p2 p3 p4 "C")
)
```


Suppose the file name is exam.lsp. At first, load the function as :

Command: (load "exam")	<i>loads the file exam.lsp</i>
------------------------	--------------------------------

And then for the sample C: SQUARE function, the new command looks like this:

Command: square
Enter the lower left corner: <i>Select a point</i>
Enter the square length : <i>Enter a distance</i>

3.2.3 AutoLISP Functions

AutoLISP provides all kinds of functions used in programming. This chapter only describes several functions used in the tool path simulation software. These functions are as follow: (Autodesk, Inc. 1992).

- Function handling : (defun *sym argument-list expr...*)

Defines an external function with the name *sym*. The function name is automatically quoted. Following the function name is a list of arguments, optionally followed by a slash and the names of one or more local symbols for the function. For instance:

(defun triac (x y) ...)	Function takes two arguments
(defun triac (/ m n) ..)	Function has two local symbols
(defun triac () ...)	Function has no arguments or local symbols

The defun function returns the name of the function being defined. The following example define new function with defun and show the values returned in AutoCAD:

(defun add20 (x) (+ 20 x)	
)	return ADD20
(add20 12)	return 32
(add20 -10)	return 10

- AutoCAD commands : (command *[arguments]* ...)

The function executes one or more AutoCAD commands and always return nil. The command function evaluates the arguments and sends them to AutoCAD in response to successive prompts. It submits command names and options as strings, 2D points as lists of two reals, and 3D points as lists of three reals. A null (“”) is equivalent to press the enter key on the keyboard. For example:

(setq pt1 '(3 3 3) pt2 '(9 9 9))	
(command “line” pt1 pt2 “”)	Draw a line from (3,3,3) to (9,9,9)

Note: If the SCRIPT command is used with the command function, it should be the last function call in the AutoLISP routine.

- User input : (getreal *[prompt]*)

This function prompts for user input of a real (floating-point) number and return that real number. For example:

(setq length (getreal))

- Display control : (princ *[expr [file-desc]]*)

This function prints a message on the text screen or to an open file and return *expr*. Princ function prints expressions in a way that is readable by functions.

- Entity handling : (entlast)

This function finds the last entity in the drawing. It is frequently used to obtain the name of a new entity which has just been added via the command function. For example:

(setq m (entlast))	Set m to the name of the last main entity in the drawing
--------------------	--

- Symbol Handling : (setq *sym1 expr1 [sym2 expr2]* ...)

This function is a basic assignment function which sets the value of *sym1* to *expr1*, *sym2* to *expr2*, and so on. It only return the last expression. For example:

(setq a 10.0)	return 10.0
(setq b (list 3 4))	return (3 4)
(setq c "triac")	return "triac"

- List manipulation : (list *expr...*)

This function creates a list from any number of expressions. It is used to define the 2D or 3D point variable. For example:

(list 1 2 3)	return (1 2 3)
---------------	----------------

- File handling : (Load *filename* [*onfailure*])

Loads a file of AutoLISP expressions.

3.2.4 Blank Size Control

The following AutoLISP language program in Figure 3.2 is provided to control the blank size for the TRIAC milling machine.

(setq width 100)
(setq height 20)
(setq length 150)
(defun C: stock(/ len wid hei)
(princ "\nEnter the New Stock Length<")(princ length)(princ ">:")
(setq len (getint))
(if len
(setq length len)

Figure 3.2. AutoLISP program for the stock size control

```

)
(princ "\nEnter the New Stock Width <")(princ width)(princ ">:")
(setq wid (getint))
( if wid
      (setq width wid)
)
(princ "\nEnter the New Stock Height<")(princ height)(princ ">:")
(setq hei (getint))
(if hei
    (setq height hei)
)
(command "erase" "l" "")
(command "color" "green")
(command "pline" "0,0" (list length 0)(list length width)(list 0
width)"c")
(command "change" "l" "" "p" "t" height "el" (-height) "")
)

```

Figure 3.2 Continued.

3.3 SCRIPT Command

A script facility is provided to allow commands to be read from a text file in AutoCAD. Utilizing this feature, users can predetermine the sequence of commands, and invoke these commands when starting AutoCAD, and run a script file within AutoCAD by using SCRIPT command. Because the script facility provides an easy way to create continuous running displays from one command to another, it is used for this simulation software to demonstrate the tool path and show the manufacture process.

3.3.1 Script File

Script files are created by using a text editor outside AutoCAD. The file name must be like “*.scr”. The lines which begin with semicolons (;) are considered a comment that provide descriptions of the file’s contents and other relevant notes. AutoCAD will ignore them when execute the script file.

For example, the script file should look like below:

snap on	; Turn on snap
grid on	; Turn on grid
linetype set continuous	; Set linetype
color red	; Select color
line 5.0, 4.0, 1.0	; Draw a line from (5.0,4.0,1.0)
1.0,1.0, 1.0	; to (1.0,1.0,1.0)

A script file directs a preordained sequence of commands either from the operating system prompt or from inside AutoCAD. It performs tasks such as: (Autodesk, Inc., 1992).

- Changing the settings or display in current drawing;
- Displaying a series of slides continuously;
- Setting up new initial drawing configurations for Units, Limits, Snap and Grid;
- Adding predetermined layers to a drawing;
- Ending one drawing and starting another.

The SCRIPT command execute a script file within AutoCAD. At first,

- Enter AutoCAD and then enter:

Command: **script**

- Respond with the script file name with an extension -- “*. SCR”, when AutoCAD prompts.

3.3.2 DELAY Command Used in Script Facility

When the continuously running displays are shown, it is found that some AutoCAD operations execute very quickly. As a result, it is difficult for people to see the tool path simulation step by step. For example, if the script file draws a short line and then erases it, the audience might not see what's happening on the screen. Therefore, DELAY command provides a rather effective function to make a sufficient pause between some operations. The DELAY command looks like this:

Command: **delay**

Delay time in milliseconds: *1000*

The delay is designed to be about one millisecond per increment. Thus, the command above will cause the next command to be delayed for one second. The larger the number is, the longer the duration of the pause is.

The DELAY command is also used in script file. For instance,

LINE

11.0, 15.0, 0.0

12.0, 20.0, 0.0

DELAY

500

LINE

1.0, 20.0, 0.0

2.0, 30.0, 0.0

This script file draws a line from point (11.0, 15.0, 0.0) to point (12.0, 20.0, 0.0) at first; then the DELAY command provides an half second pause; and finally, the script file draws an other line from (1.0, 20.0, 0.0) to (2.0, 30.0, 0.0).

3.4 C Programming Language

C programming language became known to the mass computer markets in the late 1970s. Most of today's familiar spreadsheets, databases, and word processors are written in C. Here C is used to verify NC codes and convert them into script file.

3.4.1 The Structure of C Program

The structure of the C program is described in Figure 3.3. At the first, the C program reads the NC codes, makes a Script file name to write. The second, C checks the NC code errors by blocks. If there exist an error, the computer will generate a beep and provide an error message to suggest the programmer to make a kind of change of the NC code. If the codes are correct, C will continue to convert the X, Y, XC, YC codes to real numbers. For example, it will change X1.0 to 1.0 to prepare for the further calculation. The third, this C program will calculate the lines' start point and end point, and the arcs' center points, start point and end point. This process prepares all the geometry data for the Script file. Finally, C transfers the NC code to Script file. And this Script file can be used in AutoCAD to generate the NC tool path.




Figure 3.3. Structure of C program in simulation software

3.4.2 NC Programs Error Check

Error checking is an important section in this C program. Factors needed to be considered are list in the following table (Table 3.4).

Table 3.4. Errors in NC programs for TRIAC milling machine.

<p>Format Errors</p>	<ol style="list-style-type: none"> 1. Use lower case letters instead of upper case letters. 2. Block ends without using end block letter "L". 3. Block begins without using number of block code -- N code. 4. Two or more feedrates are defined in one block. 5. Spindle speed is defined with other NC codes. 6. More than one M codes are defined in one block. 7. More than one G codes are defined in one block. 8. M code and G code are defined in one block. 9. More than one XC codes are defined in one block. 10. More than one YC codes are defined in one block. 11. More than one X, Y, Z codes are defined in one block.
<p>Syntax Errors</p>	<ol style="list-style-type: none"> 1. There are XC, YC codes in G00 block. 2. G02, G03 blocks are defined without X, Y, XC, YC codes in orders. 3. G20 block are defined without the scale. 4. G81 blocks are defined without R, E, N, X, Y, codes in orders.

Table 3.4 Continued.

<p>Geometry Data Errors</p>	<ol style="list-style-type: none"> 1. The Scale is greater than 650% or less than 0.03%. 2. The distance from the arc start point to its center point is not equal to the distance from the arc end point to its center point, or the difference are greater than 0.03mm. 3. The angle or the arc is greater than 90°. 4. The feedrate is greater than 1000 RPM.
-----------------------------	--

3.4.3 Calculations in C Program

3.4.3.1 The Calculation for the Geometry of Arcs

1. The Radius (Figure 3.4)




Figure 3.4. Start point, end point and center of an arc.

$$\sqrt{(X1 - XC)^2 + (Y1 - YC)^2} - \sqrt{(X2 - XC)^2 + (Y2 - YC)^2} \leq 0.03 \text{ mm}$$

This equation is used in C program to make sure that the distance from the arc start point to the center of the arc is equal to the distance from the arc end point to the center of the arc.

2. The Angle of Arc

$$a = \arcsin [(Y2 - Y1) / \sqrt{(X2 - XC)^2 + (Y2 - YC)^2}] \geq \pi/2$$

The equation above is used in C program to keep an arc milling operation not exceed one fourth of a circle.

3.4.3.2 The Calculation of the Geometry of the Mirror Image

1. Mirror X (Figure 3.5)




Figure 3.5. Milling a part by using Mirror X (G10) function.

$$\begin{aligned} \text{pt4: } & X4 = X1 + 2*(Xa - X1) = 2Xa - X1 & Y4 &= Y1 \\ \text{pt5: } & X5 = X2 + 2*(Xa - X2) = 2Xa - X2 & Y5 &= Y2 \\ \text{pt6: } & X6 = XC1 + 2*(Xa - XC1) = 2Xa - XC1 & Y6 &= YC1 \end{aligned}$$

The equations above are used in C program to calculate the coordinates of the mirror X image.

2. Mirror Y (Figure 3.6)




Figure 3.6. Milling a part by using Mirror Y (G12) function.

$$\text{pt4: } X4 = X1 \quad Y4 = Y1 + 2*(Ya - Y1) = 2Ya - Y1$$

$$\text{pt5: } X5 = X2 \quad Y5 = Y2 + 2*(Ya - Y2) = 2Ya - Y2$$

$$\text{pt6: } X6 = XC1 \quad Y6 = YC1 + 2*(Ya - YC1) = 2Ya - YC1$$

The equations above are used in C program to calculate the coordinates of the mirror Y image.

3. Mirror X and Mirror Y (Figure 3.7)




Figure 3.7. Milling a part by using Mirror X and Y (G10, G12) function

$$\text{pt4: } X4 = X1 + 2*(Xa - X1) = 2Xa - X1$$

$$Y4 = Y1 + 2*(Ya - Y1) = 2Ya - Y1$$

$$\text{pt5: } X5 = X2 + 2*(Xa - X2) = 2Xa - X2$$

$$Y5 = Y2 + 2*(Ya - Y2) = 2Ya - Y2$$

$$\text{pt6: } X6 = XC1 + 2*(Xa - XC1) = 2Xa - XC1$$

$$Y6 = YC1 + 2*(Ya - YC1) = 2Ya - YC1$$

The equations above are used in C program to calculate the coordinates of the mirror X and Y image.

3.4.3.3 The Calculation of Geometry of Scaling (Figure 3.8)




Figure 3.8. Milling a part by using Scaling (G20) function.

pt3: $Xa \neq X1,$ $Ya = Y1,$ $X3 = Scale * X1,$ $Y3 = Y1$

pt4: $Xa \neq X2,$ $Ya \neq Y2,$ $X4 = Scale * X2,$ $Y4 = Scale * Y2$

pt5: $Xa = X5,$ $Ya = Y5$

The equations shown above are used in C program to calculate the coordinates after executing Scaling (G20) function.

CHAPTER 4

EXAMPLES OF TOOL PATH SIMULATION

In this chapter, several examples of using the graphical tool path simulation software are provided (Figures 4.1-4.6). The purposes of create this simulation software package are to help the NC programmer, especially for students, to check syntax errors in programs, and generate a NC tool path in AutoCAD before executing the programs on the TRIAC milling machine.

According to the procedure of using this software described in Appendix C, the following examples include the figures of the milling parts, the NC programs for the parts, and the graphics of tool path simulation of these milling operations in AutoCAD environment. The NC codes include absolute positioning codes and incremental positioning. That not only clarify the conception of different types of positioning, but also ensure that the simulation software can be used in the absolute positioning as well as the incremental positioning.

The script files are transferred from NC codes by the TRIAC.exe C program in simulation software. They are mentioned in Appendixes D, E, and F. The tool path simulation is generated by executing the script files.

The tool path simulation is shown in different linetypes and different colors on computer screen.

- The stock is displayed by green continuous lines;
- The red dashed lines indicate rapid movement of the tool (G00);
- The yellow continuous lines indicate milling or drilling operation of the tool (G01, G02, G03).




Figure 4.1. Endmilling a simple part with lines and arcs, drilling operation included.

- Tool 1 6mm mill
- Tool 2 8mm mill
- Tool 3 4mm drill

The absolute NC code for the Figure 4.1 is shown below:

```

N1 M06 L
N2 M03 L
N4 G00 X1.00 Y5.00 Z1.00 L
N5 G01 Z-0.30 F5.00 L
N6 G01 Y7.00 F100 L
N7 G01 X4.00 L
N8 G02 X6.00 Y9.00 XC6.00 YC7.00 L
N9 G02 X8.00 Y7.00 XC6.00 YC7.00 L
N10 G01 X11.00 L
N11 G01 Y3.00 L
N12 G02 X9.00 Y1.00 XC9.00 YC3.00 L
N13 G01 X2.50 L
N14 G01 X1.00 Y3.00 L
N15 G01 Y5.50 L
N16 G00 Z0.30 L
N17 M05 L
N18 M06 L
N19 M03 L
N21 G00 X4.10 Y7.00 L
N22 G01 Z-0.2 F30 L
N23 G02 X6.00 Y8.10 XC6.00 YC7.00 L
N24 G02 X7.10 Y7.00 XC6.00 YC7.00 L
N25 G02 X6.00 Y5.90 XC6.00 YC7.00 L
N26 G02 X4.90 Y7.00 XC6.00 YC7.00 L
N27 G00 Z0.2 L
N28 G00 X5.60 Y7.00 L
N29 G01 Z-0.2 L
N30 G02 X6.00 Y7.40 XC6.00 YC7.00 L
N31 G02 X6.40 Y7.00 XC6.00 YC7.00 L
N32 G02 X6.00 Y6.60 XC6.00 YC7.00 L
N33 G02 X5.60 Y7.00 XC6.00 YC7.00 L
N34 G00 Z0.2 L
N35 G00 X2.40 Y3.40 L
N36 G01 Z-0.5 L
N37 G01 Y5.60 L

```

Figure 4.1 Continued

```

N38 G01 X3.60 L
N39 G01 Y3.40 L
N40 G01 X2.40 L
N41 G00 Z0.5 L
N42 G00 X3.00 Y3.50 L
N43 G01 Z-0.5 L
N44 G01 Y5.50 L
N45 G00 Z0.5 L
N46 M05 L
N47 M06 L
N48 M03 L
N50 G00 X7.00 Y4.0 L
N51 G01 Z-0.8 F50 L
N52 G01 Z0.2 L
N53 G00 X9.00 Y5.00 L
N54 G01 Z-0.8 L
N55 G01 Z0.2 L
N56 G00 Y3.00 L
N57 G01 Z-0.8 L
N58 G01 Z0.2 L
N59 G00 X0.00 Y0.00 L
N60 M05 L
N61 M02 L

```

The incremental NC code for the Figure 4.1 is shown below:

```

N1 M06 L
N2 M03 L
N4 G00 X1.00 Y5.00 Z1.00 L
N5 G01 Z-1.30 F5.00 L
N6 G01 Y2.00 F100 L
N7 G01 X3.00 L
N8 G02 X2.00 Y2.00 XC2.00 YC0.00 L
N9 G02 X2.00 Y-2.00 XC0.00 YC-2.00 L
N10 G01 X3.00 L
N11 G01 Y-4.00 L
N12 G02 X-2.00 Y-2.00 XC-2.00 YC0.00 L
N13 G01 X-6.5 L
N14 G01 X-1.50 Y2.00 L
N15 G01 Y2.5 L
N16 G00 Z0.60 L
N17 M05 L

```

Figure 4.1 Continued

N18 M06 L
 N19 M03 L
 N21 G00 X3.50 Y3.00 L
 N22 G01 Z-0.8 F30 L
 N23 G02 X1.50 Y1.50 XC1.50 YC0.00 L
 N24 G02 X1.50 Y0.00 XC0.00 YC-1.500 L
 N25 G02 X-1.50 Y-1.50 XC-1.50 YC0.00 L
 N26 G02 X-1.50 Y1.50 XC0.00 YC1.50 L
 N27 G00 Z1.0 L
 N28 G00 X-2.10 Y-4.60 L
 N29 G01 Z-1.2 L
 N30 G02 X0.70 Y0.00 XC0.80 YC0.00 L
 N31 G02 X0.80 Y0.00 XC0.00 YC-0.80 L
 N32 G02 X0.80 Y-0.80 XC-0.80 YC0.00 L
 N33 G02 X-.80 Y-0.80 XC0.00 YC0.80 L
 N34 G00 Z0.4 L
 N35 G00 X-2.80 Y-3.60 L
 N36 G01 Z-0.9 L
 N37 G01 Y2.20 L
 N38 G01 X1.20 L
 N39 G01 Y-2.20 L
 N40 G01 X-1.20 L
 N41 G00 Z1.0 L
 N42 G00 X0.60 Y0.00 L
 N43 G01 Z-1.5 L
 N44 G01 Y2.20 L
 N45 G00 Z1.0 L
 N46 M05 L
 N47 M06 L
 N48 M03 L
 N50 G00 X4.00 Y-1.60 L
 N51 G01 Z-1.8 F50 L
 N52 G01 Z1.0 L
 N53 G00 X2.00 Y1.00 L
 N54 G01 Z-1.8 L
 N55 G01 Z1.2 L
 N56 G00 Y-2.00 L
 N57 G01 Z-1.8 L
 N58 G01 Z1.0 L
 N59 G00 X-11.00 Y-3.00 L
 N60 M05 L
 N61 M02 L

Figure 4.1 Continued





Figure 4.2. Tool path simulation for Figure 4.1.



DESIGN NO.	A-2
MATERIAL	ALUMINIUM

Figure 4.2. EndMilling text on a stock surface (2mm depth)

An absolute NC code for the Figure 4.3

```
N01 M03 L
N02 G00 X3 Y14 Z2 L
N03 G01 Z-2 L
N04 G01 X8 L
N05 G00 Z2 L
N06 G00 X5 L
N07 G01 Z-2 L
N08 G01 Y6 L
N09 G00 Z2 L
N10 G00 X11 L
N11 G01 Z-2 L
N12 G01 X16 L
N13 G00 Z2 L
N14 G00 X11 L
N15 G01 Z-2 L
N16 G01 Y14 L
N17 G01 X16 L
N18 G00 Z2 L
N19 G00 X11 Y10 L
N20 G01 Z-2 L
N21 G01 X15 L
N22 G00 Z2 L
N23 G00 X24 Y12 L
N24 G01 Z-2 L
N25 G03 X22 Y14 XC22 YC12 L
N26 G03 X20 Y12 XC22 YC12 L
N27 G03 X20 Y8 XC30 YC10 L
N28 G03 X22 Y6 XC22 YC8 L
N29 G03 X24 Y8 XC22 YC8 L
N30 G00 Z2 L
N31 G00 X27 Y14 L
N32 G01 Z-2 L
N33 G01 Y6 L
N34 G00 Z2 L
N35 G00 X32 Y14 L
N36 G00 Z-2 L
N37 G01 Y6 L
```

An incremental NC code for the Figure 4.3

```
N01 M03 L
N02 G00 X3 Y14 Z2 L
N03 G01 Z-4 L
N04 G01 X5 L
N05 G00 Z4 L
N06 G00 X-3 L
N07 G01 Z-4 L
N08 G01 Y-8 L
N09 G00 Z4 L
N10 G00 X6 L
N11 G01 Z-4 L
N12 G01 Y8 L
N13 G01 X5 L
N14 G00 Z4 L
N15 G00 X-5 Y-4 L
N16 G01 Z-4 L
N17 G01 X4 L
N18 G00 Z4 L
N19 G00 X-4 Y-4 L
N20 G01 Z-4 L
N21 G01 X5 L
N22 G00 Z4 L
N23 G00 X8 Y6 L
N24 G01 Z-4 L
N25 G03 X-2 Y2 XC-2 YC0 L
N26 G03 X-3 Y-4 XC-2 YC-4 L
N27 G03 X3 Y-4 XC2 YC0 L
N28 G03 X2 Y2 XC0 YC2 L
N29 G03 X-2 Y-2 XC0 YC2 L
N30 G00 Z4 L
N31 G00 X3 Y6 L
N32 G01 Z-4 L
N33 G01 Y-8 L
N34 G00 Z4 L
N35 G00 X5 Y8 L
N36 G01 Z-4 L
N37 G01 Y-8 L
```

Figure 4.3 Continued

N38 G00 Z2 L
N39 G00 X27 Y10 L
N40 G01 Z-2 L
N41 G01 X32 L
N42 G00 Z2 L
N43 G00 X0 Y0 L
N44 M05 L
N45 M02 L

N38 G00 Z4 L
N39 G00 X-5 Y4 L
N40 G01 Z-4 L
N41 G01 X5 L
N42 G00 Z4 L
N43 G00 X-32 Y-10 L
N44 M05 L
N45 M02 L

Figure 4.3 Continued




Figure 4.4. Tool path simulation for Figure 4.3.




Figure 4.5. Endmilling a part by using mirror function

An absolute NC code for Figure 4.5.

```
N01 M03 L
N02 G00 X0 Y0 Z0.2 L
N03 G00 X0.0 Y4.25 L
N04 G01 Z-0.8 L
N05 G01 X-0.75 L
N06 G01 Y2.25 L
N07 G01 X0 L
N08 G00 Z0.2 L
N09 G00 X-0.5 L
N10 G01 Z-0.8 L
N11 G01 Y2.0 L
N12 G00 Z0.2 L
N13 G00 X0 L
N14 G01 Z-0.8 L
N15 G01 X-1.0 L
N16 G02 X-2.0 Y1.0 XC-2.0 YC2.0 L
N17 G01 Y0.0 L
N18 G00 Z0.2 L
N19 G00 Y0.25 L
N20 G01 Z-0.8 L
N21 G01 X-2.25 L
N22 G00 Z0.2 L
N23 G00 Y0 L
N24 G01 Z-0.8 L
N25 G01 Y0.5 L
N26 G01 X-4.25 L
N27 G01 Y0 L
N28 G00 Z0.2 L
N29 G00 X-1.0 Y0.0 L
N30 G01 Z-0.8 L
N31 G02 X0 Y1.0 XC0 YC0 L
N32 G00 Z0.2 L
N33 G00 X0 Y0 L
N34 G10 L
N35 G81 R03 E33 R1 X0 Y0 L
N36 G11 L
N37 G12 L
```

The incremental NC code for Figure 4.5.

```
N01 M03 L
N02 G00 X0 Y0 Z0.2 L
N03 G00 Y4.25 L
N04 G01 Z-1.0 L
N05 G01 X-0.75 L
N06 G01 Y-2.0 L
N07 G01 X0.75 L
N08 G00 Z1.2 L
N09 G00 X0.25 L
N10 G01 Z-1.0 L
N11 G01 Y-0.25 L
N12 G00 Z1.2 L
N13 G00 X0.5 L
N14 G01 Z-1.0 L
N15 G01 X-1.0 L
N16 G02 X-1.0 Y-1.0 XC-1.0 YC0 L
N17 G01 Y-1.0 L
N18 G00 Z1.2 L
N19 G00 Y0.25 L
N20 G01 Z-1.0 L
N21 G01 X-0.25 L
N22 G00 Z1.2 L
N23 G00 Y-0.25 L
N24 G01 Z-1.0 L
N25 G01 Y0.5 L
N26 G01 X-3.0 L
N27 G01 Y-0.5 L
N28 G00 Z1.2 L
N29 G00 X4.5 L
N30 G01 Z-1.0 L
N31 G02 X1.0 Y1.0 XC1.0 YC0 L
N32 G00 Z1.2 L
N33 G00 Y-1.0 L
N34 G10 L
N35 G81 R03 E33 R1 X0 Y-1.0 L
N36 G11 L
N37 G12 L
```

Figure 4.5 Continued

N38 G81 R03 E33 R1 X0 Y0 L
N39 G13 L
N40 G10 L
N41 G12 L
N42 G81 R03 E33 R1 X0 Y0 L
N43 G11 L
N44 G13 L
N45 M05 L
N46 G00 X6.0 Y5.0 L
N47 M02 L

N38 G81 R03 E33 R1 X0 Y-1.0 L
N39 G13 L
N40 G10 L
N41 G12 L
N42 G81 R03 E33 R1 X0 Y-1.0 L
N43 M05 L
N44 G11 L
N45 G13 L
N46 G00 X6.0 Y5.0 L
N47 M02 L

Figure 4.5 Continued




Figure 4.6. Tool path simulation for Figure 4.5.

CHAPTER 5

CONCLUSIONS

5.1 Contributions of the Research

The idea of this thesis was to produce a graphical simulation software that can be used for the TRIAC vertical milling machine in the department of Industrial Engineering at Texas Tech University. It is known that NC programs containing errors can cause serious problems during the communication and the machining. For instance, if the dimension of the drill operation is too deep, the cutter may drill into a clamp or a fixture. That can cause breakage of the tool and damage to the clamp or fixture. Therefore, the contributions of this graphical simulation software package are:

1. The software package prevents the students or other user to use some NC codes, such as G40, G41, whose functions are loss in TRIAC machine already.
2. The software package provides NC code inspection functions, and help the students and other user to verify their NC programs correctness during the programming process. When the error occurs, the software will stop converting NC codes into script file, and display an alarm message to tell user which part of the NC program is wrong and how to correct it.
3. The simulation software also provides graphical tool path simulation in AutoCAD environment to prevent the machine tool damage. Three views are available in the graphical tool path, such as top view, front view and the top, right, front view. Therefore, students or other users can generate the machine tool path in AutoCAD before actually machining of the part.
4. The graphical tool path simulation uses different linetypes and colors to distinguish between the cutting operation and rapid travel operation. This makes this tool path clear and powerful.

5. The stock size control function in this simulation software uses AutoLISP program and AutoCAD basic commands to generate an original stock drawing with three different views in AutoCAD.
6. Because several function keys stick up on the TRIAC machine, it is efficient for the students or other users to use this software and edit their NC programs on the computers instead of on the alpha numeric keyboard of the TRIAC machine. It also reduce the time of programming process.
7. In the current manufacturing area, some companies verify NC programs by machining and examining wooden, wax, or foam prototypes. Discrepancies between the prototypes and the intended design specifications are corrected by editing the program, and the entire process is repeated until an acceptable part is produced. (Nanga, 1992). This kind of process requires a lot of machine setup time, and the multiple manufacture time on the prototypes. Moreover, it is even founded to be costly because of the largely unavoidable expense associated with the overall manufacturing process cycle. Hence, this graphical simulation software automates the NC verification on the computer, avoids many of the arduous testing process for the prototype, and reduce the cost.
8. Without this software, this ten years old TRIAC milling machine is almost useless. Right now, it can be used to fulfill the education requirements and saves unnecessary expenses for our department buying a new one.

5.2 Suggestions for Future Research

As the current NC technology grows up rapidly, it become obvious that a programming control system is needed. The interface software provided here is effective for the students who are practicing NC programming and CNC machine operating. It is developed for the TRIAC vertical milling machine in Industrial Engineering Department at Texas Tech University. However, the programs of this simulation software do not support all the features in the NC code. A few commands that define certain geometry

features, such as rectangular circle and planes are not supported. Consequently, defining more features in this simulation software makes the interface adaptable for other NC machines.

There are several ways to define certain commands, such as using I and J codes to define circles, that are not provided in this software. Adding these features can make NC programming more flexible for programmers.

The TRIAC machine only permits 2D milling operation. As a result, the simulation software generates the NC tool path in 2D also. A future development of this interface would combine 3D curves or other 3D features.

Continuous lines on top view in the tool path represent the milling operation, and the points on the top view represent the drilling operation. The lines and the points describe the center of the cutter's path. Therefore, tool path may not look like the actual drawing of the part to be machined. The geometry data of the cutters must be provided before the simulation. A developed tool path should show the length and the diameter of the cutter, plus the depth and width of the cutting path.

Turning operation are used widely in NC technology. This is another feature suggested to be added in future research. It will make this simulation software more versatile and more applicable.

REFERENCES

- AutoCAD Release 12 AutoLISP Reference. Autodesk, Inc. Peterborough, NH. 1992.
- AutoCAD Release 12 Command Reference. Autodesk, Inc. Peterborough, NH. 1992.
- AutoCAD Release 12 Development System Programmer's Reference. Autodesk Inc. Peterborough, NH. 1992.
- AutoCAD Release 12 User Guide. Autodesk, Inc. Peterborough, NH. 1992.
- Bowerman, Robert G., Engineering Workstations: technology and application trends. Van Nostrand Reinhold, New York. 1988.
- Cubberly, William H. and Bakerjian, Ramon. Tool and Manufacturing Engineers Handbook. Society of Manufacturing Engineers, Dearborn, MI. 1989.
- Kolluri, S. P. "Simulation of CNC Controller Features in Graphics-Based Programming," Computers in Industry. 1989, Vol. 11, No. 2, pp.135.
- McMahon, Chris and Browne, Jimmie. CAD/CAM From Principles to Practice. Addison-Wesley Publishers Ltd, Reading, MA. 1993.
- Nanga, Prashant. NC Tool Path Simulation for Automated Programmable Tools (APT) Using SmartCAM during Milling Process. University of Southern Mississippi. 1992.
- Perry, Greg. Moving from C to C++. SAMS Publishing, Indianapolis, IN. 1992.
- Smith, Graham T. CNC Machining Technology. Springer-Verlag, New York. 1993.
- Smith, Graham T. CNC Machining Technology. Springer-Verlag Limited London, Germany. 1993.
- TRIAC Programming Instruction and Maintenance Manual. DENFORD Machine Tools Limited. England, 1985.

APPENDIX A

THE C PROGRAM FOR THE SIMULATION SOFTWARE

```

/*****
    This program converts a file containing NC codes into
    an AutoCAD "SCRIPT" file -- "*.scr". (limited conversion).
*/
/*****
/*----- */
/* Triac M/C information */
/*----- */
/* (All Dimensions in 'mm' )
    Axis Travel :
        X = 290 mm
        Y = 170
        Z = 235

    Spindle Speed : 100 - 2500 RPM

    Feed Rate :
        G00 = 1000 mm/min
        G01 = 0 - 1000 mm/min

    Table Dimentions :
        Length = 500 mm
        Width = 160
        Spindle to Table = 280

    Table Slots : 10mm T-Slots

    M/C Dimensions :
        L = 990 mm
        W = 710
        H = 980
*/
/*****
/

#include<stdio.h>
#include<string.h>
#include<math.h>

```

```
#include<stdlib.h>
```

```
#define M00    0
#define M02    1
#define M03    2
#define M04    3
#define M05    4
#define M06    5
```

```
#define G00    6
#define G01    7
#define G02    8
#define G03    9
#define G04   10
#define G10   11
#define G11   12
#define G12   13
#define G13   14
#define G20   15
#define G71   16
#define G81   17
#define G90   18
#define G91   19
#define G54   20
```

```
#define ABSOLUTE 18
#define RELATIVE 19
#define RAPID    20
#define VFEED    21
```

```
/* global variables */
```

```
char *gazValidMCodes[] = {"M00","M0","M02","M2","M03","M3","M04","M4",
                          "M05", "M5",""};
```

```
char *gazInvalidMCodes[] = {"M06","M6","M20","M21",""};
```

```
char *gazValidGCodes[] = {"G00","G0","G01","G1","G02","G2","G03","G3",
                          "G04","G4","G10","G11","G12","G13","G20"
                          "G71","G81","G90","G91",""};
```

```
char *gazInValidGCodes[] = {"G21","G40","G41","G42","G54","G70","G79","G80",
                          "G82","G83","G84","G98","G99",""};
```

```
char gzLineBuff[100], gzNcFileName[15], gzScriptFileName[15],
gazArguments[10][10];
```

```
/* gzLineBuff[100] is defined as every block of the NC program.
```

```
gzNcFileName is the NC code file name.
```

```

    gzScriptFileName is the Script file name.
    gazArguments[10][10] is defined as each NC code in one block.*/
FILE *gfpNcFile, *gfpScriptFile;
float gfPresentX, gfPresentY, gfPreviousX, gfPreviousY, gfArcCentX, gfArcCentY;
float gfPresentZ, gfPreviousZ;
/* gfPresentX is the current value in X direction;
   gfPresentY is the current value in Y direction;
   gfPresentZ is the current value in Z direction;
   gfPreviousX is the previous value in X direction;
   gfPreviousY is the previous value in Y direction;
   gfPreviousZ is the previous value in Z direction;
   gfArcCentX is the center point of an arc in X direction;
   gfArcCentY is the center point of an arc in Y direction;
   gfArcCentZ is the center point of an arc in Z direction. */

int giMovementType, giLastFeedMovement;
float gfFeedRate, Scale, ScaleX, ScaleY;

```

```

/* Functions Used */
/*

```

```

ExitWithError(char zError[100]) -----1
MakeScriptFileName( ) -----2
NcCommand(char zCommand[10]) -----3
CheckForGeneralErrors(int iNumOfArgs) -----4
float ConvertStringToFloat(char zBuff[20],int I) -----5
SetPresentPointsFromArguments(int I) -----6
ChangePreviousPoints( ) -----7
float Dist1( ) -----8
float Dist2( ) -----9
CheckForArcSyntax( ) -----10
CommandDelay( ) -----11
CheckForFeed(int iLastArgNum) -----12
CheckLineSyntaxAndGenerateScriptCode( ) -----13

*/

```

```

ExitWithError(char zError[100]) /* 1 */
{

```

```

printf("\n\7Error: %s",zError);
exit(1);
}
/* end print error and exit */

```

```

void MakeScriptFileName( )                                /* 2*/
{
    char *ptr;
    strcpy (gzScriptFileName, gzNcFileName);
    ptr=strchr(gzScriptFileName, '.');
    if (ptr!=NULL)
        gzScriptFileName[ptr-gzScriptFileName]=0;
    strcat(gzScriptFileName, ".SCR");
}/* end of creating script file name and checking 'NC' extension */

```

```

NcCommand(char zCommand[10])                              /* 3 */
{
    int i;

    /* check for valid 'M' codes */
    if(!strcmp(zCommand, "M00") || !strcmp(zCommand, "M0"))
        return M00;
    else
        if(!strcmp(zCommand, "M02") || !strcmp(zCommand, "M2"))
            return M02;
        else
            if(!strcmp(zCommand, "M03") || !strcmp(zCommand, "M3"))
                return M03;
            else
                if(!strcmp(zCommand, "M04") || !strcmp(zCommand, "M4"))
                    return M04;
                else
                    if (!strcmp(zCommand, "M05") || !strcmp(zCommand, "M5"))
                        return M05;
                    else
                        if(!strcmp(zCommand, "M06") || !strcmp(zCommand, "M6"))
                            return M06;

    else /* check for valid 'G' codes */
        if(!strcmp(zCommand, "G00") || !strcmp(zCommand, "G0"))
            return G00;

```

```

else
if(!strcmp(zCommand,"G01") || !strcmp(zCommand,"G1"))
    return G01;
else
if(!strcmp(zCommand,"G02") || !strcmp(zCommand,"G2"))
    return G02;
else
if(!strcmp(zCommand,"G03") || !strcmp(zCommand,"G3"))
    return G03;
else
if(!strcmp(zCommand,"G04") || !strcmp(zCommand,"G4"))
    return G04;
else
if(!strcmp(zCommand,"G10"))
    return G10;
else
if(!strcmp(zCommand,"G11"))
    return G11;
else
if(!strcmp(zCommand,"G12"))
    return G12;
else
if(!strcmp(zCommand,"G13"))
    return G13;
else
if(!strcmp(zCommand,"G20"))
    return G20;
else
if(!strcmp(zCommand,"G71"))
    return G71;
else
if(!strcmp(zCommand,"G81"))
    return G81;
else
if(!strcmp(zCommand,"G90"))
    return G90;
else
if(!strcmp(zCommand,"G91"))
    return G91;
else
if(!strcmp(zCommand,"G54"))
    return G54;
else /* invalid entry */

```

```

        return 0;
    }/* end of checking for invalid 'NC' codes */

```

```

CheckForGeneralErrors(int iNumOfArgs)                                /* 4 */
{
    int i j, iCount;

    /* check for any character > 'Z' i.e. no lower case letters */
    for(i = 0;i < strlen(gzLineBuff);i++)
        if(gzLineBuff[i] > 'Z')
            ExitWithError("Invalid input..., no lower case letters.\n");

    /* check for the end of the block with the letter 'L'*/
    if(gazArguments[iNumOfArgs-1][0] != 'L')
        ExitWithError("Please end with 'L'.\n");

    /* check for block# */
    if(gazArguments[0][0] != 'N')
        ExitWithError("No Block number specified\n");

    /* check for two block-#'s */
    for(i = 1;i < iNumOfArgs;i++)
        if(gazArguments[i][0] == 'N')
            ExitWithError("Invalid Code...Too many Block# Spec's.\n");

    /* check for the Spindle speed (S-word) and NC-code in one block. */
    for (i = 1;i < iNumOfArgs; i++)
        if((gazArguments[i][0] == 'S') && (iNumOfArgs > 2))
            ExitWithError("NC codes with S-word not accepted.\n");

    /* check for more than two feed-rate */
    iCount = 0;
    for(i = 1;i < iNumOfArgs;i++)
        if(gazArguments[i][0] == 'F')
            iCount++;
    if(iCount > 1)
        ExitWithError("Invalid Code (too-many feed rate)\n");

    /* check for the feed-rate should be specified at the end of the block*/
    for(i = 1; i < iNumOfArgs; i++)
        if((gazArguments[i][0] == 'F') && (i != iNumOfArgs-2))

```

```

        ExitWithError(" Feed rate should be at the end of the block.");

/* check for valid 2nd-argument */
if((gazArguments[1][0] != 'M') && (gazArguments[1][0] != 'G'))
    ExitWithError("Invalid Code...\n");

/* check for more than two G-arg */
iCount = 0;
for(i = 1; i < iNumOfArgs; i++)
    if(gazArguments[i][0] == 'G')
        iCount++;
if(iCount > 1)
    ExitWithError("Invalid Code (too-many G-arguments)\n");

/* check for G-code and M-code in same block */
iCount=0;
for(i=1; i<iNumOfArgs; i++)
    if(gazArguments[i][0] == 'G')
    {
        for (j=1; j<iNumOfArgs; j++)
        {
            if( gazArguments[j][0] == 'M')
                ExitWithError("G-code and M-code should not be in the same block.\n");
        }
    }

/*check for blank lines*/
if(!(strcmp(gzLineBuff, "\n")))
    ExitWithError("Blank lines are not accept when transfer to TRIAC.\n");

/* if 2nd-arg == "G02"/"G03" */
if(!strcmp(gazArguments[i], "G02") || !strcmp(gazArguments[i], "G03"))
if(iNumOfArgs != 6)
    ExitWithError("Code Missing\n");

/* if 2nd-arg == "G01"/"G00" */
if(!strcmp(gazArguments[i], "G00") || !strcmp(gazArguments[i], "G01"))
{
if(iNumOfArgs < 3)
    ExitWithError("Code Missing/Remove the line\n");
for(i = 2; i < iNumOfArgs; i++)
if( ((gazArguments[i][0] == 'X') || (gazArguments[i][0] == 'Y')) &&

```

```

(gazArguments[i][1] == 'C') )
    ExitWithError("Invalid Code...NoArcCode Please\n");
}

/* check for more than two X-arg */
iCount = 0;
for(i = 2;i < iNumOfArgs;i++)
    if( (gazArguments[i][0] == 'X') && (gazArguments[i][1] != 'C') )
        iCount++;
if(iCount > 1)
    ExitWithError("Invalid Code (too-many X-arguments)\n");

/* check for more than two Y-arg */
iCount = 0;
for(i = 2;i < iNumOfArgs;i++)
    if( (gazArguments[i][0] == 'Y') && (gazArguments[i][1] != 'C') )
        iCount++;
if(iCount > 1)
    ExitWithError("Invalid Code (too-many Y-arguments)\n");

/* check for more than two XC-arg */
iCount = 0;
for(i = 2;i < iNumOfArgs;i++)
    if( (gazArguments[i][0] == 'X') && (gazArguments[i][1] == 'C') )
        iCount++;
if(iCount > 1)
    ExitWithError("Invalid Code (too-many XC-arguments)\n");

/* check for more than two YC-arg */
iCount = 0;
for(i = 2;i < iNumOfArgs;i++)
    if( (gazArguments[i][0] == 'Y') && (gazArguments[i][1] == 'C') )
        iCount++;
if(iCount > 1)
    ExitWithError("Invalid Code (too-many YC-arguments)\n");

/* check for more than two Z-arg */
iCount = 0;
for(i = 2;i < iNumOfArgs;i++)
    if(gazArguments[i][0] == 'Z')
        iCount++;
if(iCount > 1)

```



```
ExitWithError("Invalid Code (too-many Z-arguments)\n");
```

```
/*check for G81 format*/  
for (i=1; i<iNumOfArgs; i++)  
{  
    if(!strcmp(gazArguments[1],"G81"))  
    {  
        if((gazArguments[2][0]!='R')||(gazArguments[3][0]!='E')||  
            (gazArguments[4][0]!='R'))  
            ExitWithError("Invalid format for G81.\n");  
    }  
}  
  
/* end of checking for general commands in a block */
```

```
float ConvertStringToFloat(char zBuff[20],int I)                /* 5 */  
{  
    int j;  
    int len;  
    len = strlen(zBuff);  
    for(j = 0;j <= (len - i);j++)  
        zBuff[j] = zBuff[j+i];  
    return atof(zBuff);  
}/* end of converting */
```

```
SetPresentPointsFromArguments(int i)                            /* 6 */  
{  
    if((gazArguments[i][0] == 'X') && (gazArguments[i][1] == 'C'))  
    {  
        if(giMovementType == ABSOLUTE)  
            gfArcCentX = ConvertStringToFloat(gazArguments[i],2);  
        else  
            gfArcCentX = gfPreviousX +ConvertStringToFloat(gazArguments[i],2);  
    }  
    else  
    if((gazArguments[i][0] == 'Y') && (gazArguments[i][1] == 'C'))  
    {  
        if(giMovementType == ABSOLUTE)
```

```

        gfArcCentY = ConvertStringToFloat(gazArguments[i],2);
    else
        gfArcCentY = gfPreviousY + ConvertStringToFloat(gazArguments[i],2);
    }
    else
    if(gazArguments[i][0] == 'X')
    {
        if(giMovementType == ABSOLUTE)
            gfPresentX = ConvertStringToFloat(gazArguments[i],1);
        else
            gfPresentX = gfPresentX + ConvertStringToFloat(gazArguments[i],1);
    }
    else
    if(gazArguments[i][0] == 'Y')
    {
        if(giMovementType == ABSOLUTE)
            gfPresentY = ConvertStringToFloat(gazArguments[i],1);
        else
            gfPresentY = gfPresentY + ConvertStringToFloat(gazArguments[i],1);
    }
    else
    if(gazArguments[i][0] == 'Z')
    {
        if(giMovementType == ABSOLUTE)
            gfPresentZ = ConvertStringToFloat(gazArguments[i],1);
        else
            gfPresentZ = gfPresentZ + ConvertStringToFloat(gazArguments[i],1);
    }
    else
    if(gazArguments[i][0] == 'F')
    {
        gfFeedRate = ConvertStringToFloat(gazArguments[i],1);
        if(gfFeedRate < 1.0)
            ExitWithError("Feed Rate Not Specified");
        if(gfFeedRate > 1000.0)
            ExitWithError("Maximum Feed Rate Exceeded");
        if((gfFeedRate > 300.0) && (giLastFeedMovement == VFEEED))
            ExitWithError("Feed Rate; Too High");
        printf("\n\tChangeIn FEED");
    }
    else
    if(!(strcmp(gazArguments[i], "G20")))
    {

```

```

Scale = ConvertStringToFloat(gazArguments[i+1],0);
if(Scale<0.01)
    ExitWithError("Scale is too small.\n");
if(Scale>650)
    ExitWithError("Scale is too large.\n");
}
}/* end of converting arguments to Present-Points */

```

```

ChangePreviousPoints( )                                /* 7 */
{
    gfPreviousX = gfPresentX;
    gfPreviousY = gfPresentY;
    gfPreviousZ = gfPresentZ;
}/* end of changing previous-points = present-points */

```

```

float Dist1( )                                         /* 8 */
{
    float fTmp1,fTmp2,fTmp;
    fTmp1 = (gfArcCentX - gfPreviousX);
    fTmp1*=fTmp1;
    fTmp2 = (gfArcCentY - gfPreviousY);
    fTmp2*=fTmp2;
    fTmp = (sqrt(fTmp1 + fTmp2));
    return fTmp;
}/* end of radius from CenterPt -> StartPt */

```

```

float Dist2( )                                         /* 9 */
{
    flaot fTmp1,fTmp2,fTmp;
    fTmp1 = (gfArcCentX - gfPresentX);
    fTmp1*=fTmp1;
    fTmp2 = (gfArcCentY - gfPresentY);
    fTmp2*=fTmp2;
    fTmp = (sqrt(fTmp1 + fTmp2));
    return fTmp;
}

```

```
}/* end of radius from CenterPt -> EndPt */
```

```
CheckForArcSyntax( )                                /* 10 */
{
    if( (gazArguments[2][0] == 'X') && (gazArguments[3][0] == 'Y'))
    if( (gazArguments[4][0] == 'X') && (gazArguments[4][1] == 'C'))
    if( (gazArguments[5][0] == 'Y') && (gazArguments[5][1] == 'C'))
        return 1;
    ExitWithError("Invalid Arc Argument...");
}/* end of checking for arc syntax */
```

```
CommandDelay( )                                    /* 11 */
{
    fprintf(gfpScriptFile,"Delay\n500\n");
}/* end of command-delay */
```

```
CheckForFeed(int iLastArgNum)                      /* 12 */
{
    if(giLastFeedMovement == RAPID)
    if(gazArguments[iLastArgNum-2][0] != 'F')
        ExitWithError("Feed not Specified");
    giLastFeedMovement = VFEED;
}/* end of checking for feed-set */
```

```
CheckLineSyntaxAndGenerateScriptCode( )           /* 13 */
{
    static int inrepeat=0, XMirror, YMirror;
    int flag;
    static char RBegin[10], REnd[10], Repeat[10];
    int iAction,iNumOfArgs,iCount,i, Range;
    static float XIncrease,YIncrease,ScaleX=1.0,ScaleY=1.0;
    float fRad1,fRad2;
    char zBuff1[10],zBuff2[10],zBuff3[10],zBuff4[10],zBuff5[10],zBuff6[10],
        zBuff7[10],zBuff8[10];
```

```

if(gzLineBuff[strlen(gzLineBuff) -1] == 10)
    gzLineBuff[strlen(gzLineBuff)-1] = 0; /* remove new-line character*/
iNumOfArgs = sscanf(gzLineBuff,"%s %s %s %s %s %s %s %s",
    zBuff1,zBuff2,zBuff3,zBuff4,zBuff5,zBuff6,zBuff7,zBuff8);
/*read NC code by block*/

sscanf(gzLineBuff,"%s %s %s %s %s %s %s %s",
    gazArguments[0],gazArguments[1],gazArguments[2],gazArguments[3],
    gazArguments[4],gazArguments[5],gazArguments[6],gazArguments[7]);
/* build argument list */

flag=0;
if (inrepeat == 1)
{
    if((strcmp(gazArguments[0],RBegin) >= 0&&strcmp(gazArguments[0],REnd) <= 0)
        llstrcmp(gazArguments[0],Repeat)>0)
        flag=1;
    else
        flag=0;
}
if (inrepeat==0)
    flag=1;
if (flag==1)
{
    printf("\nChecking Syntax: %s",gzLineBuff);
    CheckForGeneralErrors(iNumOfArgs);
    if(!(iAction = NcCommand(gazArguments[1])))
        ExitWithError("Invalid Command Code....\n");
    switch(iAction)
    {
        case M00 :
        case M02 :
            printf(" //Program Stop");
            return 0;
        case M03 :
            printf(" //Spindle Forward");
            break;
        case M04 :
            printf(" //Spindle Reverse");
            break;
        case M05 :
            printf(" //Spindle Stop");
            break;
    }
}

```

```

case M06 :
    printf(" //Tool Change");
    break;
case G00 :
    if (inrepeat == 0)
    {
        for(i = 2;i < iNumOfArgs-1;i++)
            SetPresentPointsFromArguments(i);
    }

    if (inrepeat == 1)
    {
        for(i = 2;i < iNumOfArgs-1;i++)
        {
            if((XMirror== 1)&&(gazArguments[i][0]== 'X'))
            {
                SetPresentPointsFromArguments(i);
                gfPresentX = (2*XIncrease - gfPresentX);
            }
            if((YMirror== 1)&&(gazArguments[i][0]== 'Y'))
            {
                SetPresentPointsFromArguments(i);
                gfPresentY =(2*YIncrease - gfPresentY);
            }
            if((ScaleX!=1)&&(gfPresentX!=XIncrease))
            {
                SetPresentPointsFromArguments(i);
                gfPresentX = ScaleX * gfPresentX;
            }
            if((ScaleY!=1)&&(gfPresentY!=YIncrease))
            {
                SetPresentPointsFromArguments(i);
                gfPresentY = ScaleY * gfPresentY;
            }
            else
            {
                SetPresentPointsFromArguments(i);
            }
        }
    }

    fprintf(gfpScriptFile,"LINETYPE\nSET\nHIDDEN\n\n");
    fprintf(gfpScriptFile,"COLOR\nRED\n");
    fprintf(gfpScriptFile,"LINE\n%f,%f,%f\n%f,%f,%f\n\n",

```

```

        gfPreviousX,gfPreviousY,gfPreviousZ,
        gfPresentX,gfPresentY,gfPresentZ);
    printf(" //Linear Rapid Movement");
    giLastFeedMovement = RAPID;
    ChangePreviousPoints( );
    break;
case G01 :
    if(inrepeat == 0)
    {
        for(i = 2;i < iNumOfArgs-1;i++)
        SetPresentPointsFromArguments(i);
    }

    if(inrepeat == 1)
    {
        for(i = 2;i < iNumOfArgs-1;i++)
        {
            if((XMirror==1)&&(gazArguments[i][0]=='X'))
            {
                SetPresentPointsFromArguments(i);
                gfPresentX = (2*XIncrease - gfPresentX);
            }
            if((YMirror==1)&&(gazArguments[i][0]=='Y'))
            {
                SetPresentPointsFromArguments(i);
                gfPresentY =(2*YIncrease - gfPresentY);
            }
            if((ScaleX!=1)&&(gfPresentX!=XIncrease))
            {
                SetPresentPointsFromArguments(i);
                gfPresentX = ScaleX * gfPresentX;
            }
            if((ScaleY!=1)&&(gfPresentY!=YIncrease))
            {
                SetPresentPointsFromArguments(i);
                gfPresentY = ScaleY * gfPresentY;
            }
        }
        else
        {
            SetPresentPointsFromArguments(i);
        }
    }
}

```

```

fprintf(gfpScriptFile,"LINETYPE\nSET\nCONTINUOUS\n\n");
fprintf(gfpScriptFile,"COLOR\nYELLOW\n");
fprintf(gfpScriptFile,"LINE\n%f,%f,%f\n%f,%f,%f\n\n",
    gfPreviousX,gfPreviousY,gfPreviousZ,
    gfPresentX,gfPresentY,gfPresentZ);
printf(" //Linear (VariableFeed) Movement");
CommandDelay( );
ChangePreviousPoints( );
break;
case G02 :
    CommandDelay( );
    CheckForArcSyntax( );
    if(abs(Dist1( ) - Dist2( )) > 0.03)
        ExitWithError("Invalid ArcRADIUS...\n");
    if(inrepeat ==0)
    {
        for(i = 2;i < iNumOfArgs-1;i++)
            SetPresentPointsFromArguments(i);
    }

    if(inrepeat == 1)
    {
        for(i = 2;i < iNumOfArgs-1;i++)
        {
            if(XMirror==1)
            {
                if(gazArguments[i][0]=='X'&&gazArguments[i][1]=='C')
                {
                    SetPresentPointsFromArguments(i);
                    gfArcCentX = 2*XIncrease - gfArcCentX;
                }
                if(gazArguments[i][0]=='X')
                {
                    SetPresentPointsFromArguments(i);
                    gfPresentX = (2*XIncrease - gfPresentX);
                }
            }
        }
        if(YMirror==1)
        {
            if(gazArguments[i][0]=='Y'&&gazArguments[i][1]=='C')
            {
                SetPresentPointsFromArguments(i);
                gfArcCentY = 2*YIncrease - gfArcCentY;
            }
        }
    }

```



```

        }
        if(gazArguments[i][0]=='Y')
        {
            SetPresentPointsFromArguments(i);
            gfPresentY = (2*YIncrease - gfPresentY);
        }
    }

    if((ScaleX!=1)&&(gfPresentX!=XIncrease))
    {
        SetPresentPointsFromArguments(i);
        gfPresentX = ScaleX * gfPresentX;
    }

    if((ScaleY!=1)&&(gfPresentY!=YIncrease))
    {
        SetPresentPointsFromArguments(i);
        gfPresentY = ScaleY * gfPresentY;
    }
    else
    {
        SetPresentPointsFromArguments(i);
    }
}

fprintf(gfpScriptFile,"LINETYPE\nSET\nCONTINUOUS\n\n");
fprintf(gfpScriptFile,"COLOR\nYELLOW\n");

fprintf(gfpScriptFile,"ARC\nC\n%f,%f,%f\n",
gfArcCentX,gfArcCentY,gfPresentZ);
if(((XMirror==0)&&(YMirror==0))||((XMirror==1)&&(YMirror==1)))
{
    fprintf(gfpScriptFile,"%f,%f\n",gfPresentX,gfPresentY);
    fprintf(gfpScriptFile,"%f,%f\n",gfPreviousX,gfPreviousY);
    printf(" //ClockWise Arc");
}
else
{
    fprintf(gfpScriptFile,"%f,%f\n",gfPreviousX,gfPreviousY);
    fprintf(gfpScriptFile,"%f,%f\n",gfPresentX,gfPresentY);
    printf(" //Counter-ClockWise Arc");
}

```

```

        ChangePreviousPoints( );
    break;

case G03 :
    CommandDelay( );

    CheckForArcSyntax( );

    if(abs(Dist1( ) - Dist2( )) > 0.03)
        ExitWithError("Invalid ArcRADIUS...\n");
    if(inrepeat ==0)
    {
        for(i = 2;i < iNumOfArgs-1;i++)
            SetPresentPointsFromArguments(i);
    }

    if(inrepeat == 1)
    {
        for(i = 2;i < iNumOfArgs-1;i++)
        {
            if(XMirror==1)
            {
                if(gazArguments[i][0]=='X' && gazArguments[i][1]=='C')
                {
                    SetPresentPointsFromArguments(i);
                    gfArcCentX = 2*XIncrease - gfArcCentX;
                }
                if(gazArguments[i][0]=='X')
                {
                    SetPresentPointsFromArguments(i);
                    gfPresentX = (2*XIncrease - gfPresentX);
                }
            }
        }
        if(YMirror==1)
        {
            if(gazArguments[i][0]=='Y' && gazArguments[i][1]=='C')
            {
                SetPresentPointsFromArguments(i);
                gfArcCentY = 2*YIncrease - gfArcCentY;
            }
            if(gazArguments[i][0]=='Y')
            {
                SetPresentPointsFromArguments(i);
            }
        }
    }

```

```

        gfPresentY = (2*YIncrease - gfPresentY);
    }
}

if((ScaleX!=1)&&(gfPresentX!=XIncrease))
{
    SetPresentPointsFromArguments(i);
    gfPresentX = ScaleX * gfPresentX;
}

if((ScaleY!=1)&&(gfPresentY!=YIncrease))
{
    SetPresentPointsFromArguments(i);
    gfPresentY = ScaleY * gfPresentY;
}
else
{
    SetPresentPointsFromArguments(i);
}
}
}

fprintf(gfpScriptFile,"LINETYPE\nSET\nCONTINUOUS\n\n");
fprintf(gfpScriptFile,"COLOR\nYELLOW\n");
fprintf(gfpScriptFile,"ARC\nC\n%f,%f,%f\n",
    gfArcCentX,gfArcCentY,gfPresentZ);

if(((XMirror==0)&&(YMirror==0))||((XMirror==0)&&(YMirror==0)))
{
    fprintf(gfpScriptFile,"%f,%f\n",gfPreviousX,gfPreviousY);
    fprintf(gfpScriptFile,"%f,%f\n",gfPresentX,gfPresentY);
    printf(" //Counter-ClockWise Arc");
}
else
{
    fprintf(gfpScriptFile,"%f,%f\n",gfPresentX,gfPresentY);
    fprintf(gfpScriptFile,"%f,%f\n",gfPreviousX,gfPreviousY);
    printf(" //ClockWise Arc");
}

ChangePreviousPoints( );
break;

```

```

case G04 :
    printf(" //Tool Dwell");
    break;
case G10 :
    XMirror =1;
    printf("// Mirror X function");
    break;
case G11:
    printf("// Cancel Mirror X");
    XMirror=0;
    break;
case G12 :
    YMirror =1;
    printf("// Mirror Y function");
    break;
case G13 :
    printf("// Cancel Mirror Y");
    YMirror = 0;
    break;
case G20 :
    printf("// Scale function");
    ScaleX=ScaleY = ConvertStringToFloat(gazArguments[2],0)/100.00;
    break;
case G54 :
    ChangePreviousPoints( );
    for(i = 2;i < iNumOfArgs-1;i++)
        SetPresentPointsFromArguments(i);
    fprintf(gfpScriptFile,"LINETYPE\nSET\nHIDDEN\n\n");
    fprintf(gfpScriptFile,"COLOR\nRED\n");
    fprintf(gfpScriptFile,"LINE\n%f,%f,%f\n%f,%f,%f\n\n",
        gfPreviousX,gfPreviousY,gfPreviousZ,gfPresentX,gfPresentY,
        gfPresentZ);
    printf(" //GOTO Floating m/c Reference Pt.; Rapid Movement");
    giLastFeedMovement = RAPID;
    break;
case G71 :
    printf(" //Metric Units");
    break;
case G90 :
    giMovementType = ABSOLUTE;
    printf(" //Absolute Point Input");
    break;
case G91 :

```

```

        giMovementType = RELATIVE;
        printf(" //Relative Point Input");
        break;
case G81 :
        inrepeat=1;
        strcpy(Repeat, gazArguments[0]);
        strcpy(RBegin,gazArguments[2]);
        RBegin[0] = 'N';
        strcpy(REnd,gazArguments[3]);
        REnd[0] = 'N';
        XIncrease = ConvertStringToFloat(gazArguments[5],1);
        YIncrease = ConvertStringToFloat(gazArguments[6],1);
        printf("//Repeat Function");

        fseek(gfpNcFile,0,SEEK_SET);

    /* end of switch */
}

return 1;
}/* end of checking line syntax & write Script code */

/*----- Start of Main( ) ----- */
main( )
{
    /* initialize global variables */
    gfPreviousX = gfPresentX = 5;
    gfPreviousY = gfPresentY = 5;
    gfPreviousZ = gfPresentZ = 0.5;
    giMovementType = ABSOLUTE;
    giLastFeedMovement = RAPID;

    printf("\n\n\n\n\n\tEnter NC-code FileName: ");
    scanf("%s",gzNcFileName);
    MakeScriptFileName( );
    printf("\n NcFile->%s   ScriptFile->%s\n",gzNcFileName,gzScriptFileName);
    if((gfpNcFile = fopen(gzNcFileName,"r")) == NULL)
        ExitWithError("Unable to OPEN 'NC' file for Reading");
    if((gfpScriptFile = fopen(gzScriptFileName,"w")) == NULL)
        ExitWithError("Unable to OPEN 'Script' file for Writing");
}

```

```

while( fgets(gzLineBuff,70,gfpNcFile) != NULL )
    if(! CheckLineSyntaxAndGenerateScriptCode( ))
        break;

printf("\n\nNcFile->%s  ScriptFile->%s\n",gzNcFileName,gzScriptFileName);
fclose(gfpNcFile);
fclose(gfpScriptFile);
}/* end of main */

/***** End of Program *****/

```

APPENDIX B

THE AUTOCAD DRAWING OF THE ORIGINAL STOCK




Figure B.1.1. The AutoCAD drawing of the original stock

APPENDIX C

THE SCRIPT FILE FOR FIGURE 5.1

LINETYPE	COLOR
SET	YELLOW
HIDDEN	
	LINE
COLOR	1.000000,7.000000,-0.300000
RED	4.000000,7.000000,-0.300000
LINE	
50.000000,50.000000,5.000000	Delay
1.000000,5.000000,1.000000	500
	Delay
LINETYPE	500
SET	LINETYPE
CONTINUOUS	SET
	CONTINUOUS
COLOR	
YELLOW	COLOR
LINE	YELLOW
1.000000,5.000000,1.000000	ARC
1.000000,5.000000,-0.300000	C
	6.000000,7.000000,-0.300000
Delay	6.000000,9.000000
500	4.000000,7.000000
LINETYPE	Delay
SET	500
CONTINUOUS	LINETYPE
	SET
COLOR	CONTINUOUS
YELLOW	
LINE	COLOR
1.000000,5.000000,-0.300000	YELLOW
1.000000,7.000000,-0.300000	ARC
	C
Delay	6.000000,7.000000,-0.300000
500	8.000000,7.000000
LINETYPE	6.000000,9.000000
SET	LINETYPE
CONTINUOUS	SET
	CONTINUOUS

COLOR
YELLOW
LINE
8.000000,7.000000,-0.300000
11.000000,7.000000,-0.300000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
11.000000,7.000000,-0.300000
11.000000,3.000000,-0.300000

Delay
500
Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
9.000000,3.000000,-0.300000
9.000000,1.000000
11.000000,3.000000
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
9.000000,1.000000,-0.300000
2.500000,1.000000,-0.300000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
2.500000,1.000000,-0.300000
1.000000,3.000000,-0.300000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
1.000000,3.000000,-0.300000
1.000000,5.500000,-0.300000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
1.000000,5.500000,-0.300000
1.000000,5.500000,0.300000

LINETYPE
SET
HIDDEN

COLOR
RED

LINE
1.000000,5.500000,0.300000
4.100000,7.000000,0.300000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
4.100000,7.000000,0.300000
4.100000,7.000000,-0.200000

Delay
500
Delay
500

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
6.000000,7.000000,-0.200000
6.000000,8.100000
4.100000,7.000000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
6.000000,7.000000,-0.200000
7.100000,7.000000
6.000000,8.100000
Delay

500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
6.000000,7.000000,-0.200000
6.000000,5.900000
7.100000,7.000000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
6.000000,7.000000,-0.200000
4.900000,7.000000
6.000000,5.900000
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
4.900000,7.000000,-0.200000
4.900000,7.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
4.900000,7.000000,0.200000

5.600000,7.000000,0.200000

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

LINE

5.600000,7.000000,0.200000

5.600000,7.000000,-0.200000

Delay

500

Delay

500

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

ARC

C

6.000000,7.000000,-0.200000

6.000000,7.400000

5.600000,7.000000

Delay

500

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

ARC

C

6.000000,7.000000,-0.200000

6.400000,7.000000

6.000000,7.400000

Delay

500

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

ARC

C

6.000000,7.000000,-0.200000

6.000000,6.600000

6.400000,7.000000

Delay

500

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

ARC

C

6.000000,7.000000,-0.200000

5.600000,7.000000

6.000000,6.600000

LINETYPE

SET

HIDDEN

COLOR

RED

LINE

5.600000,7.000000,-0.200000

5.600000,7.000000,0.200000

LINETYPE

SET

HIDDEN

COLOR

RED

LINE

5.600000,7.000000,0.200000

2.400000,3.400000,0.200000

LINETYPE	3.600000,5.600000,-0.500000
SET	3.600000,3.400000,-0.500000
CONTINUOUS	
COLOR	Delay
YELLOW	500
LINE	LINETYPE
2.400000,3.400000,0.200000	SET
2.400000,3.400000,-0.500000	CONTINUOUS
Delay	COLOR
500	YELLOW
LINETYPE	LINE
SET	3.600000,3.400000,-0.500000
CONTINUOUS	2.400000,3.400000,-0.500000
COLOR	Delay
YELLOW	500
LINE	LINETYPE
2.400000,3.400000,-0.500000	SET
2.400000,5.600000,-0.500000	HIDDEN
Delay	COLOR
500	RED
LINETYPE	LINE
SET	2.400000,3.400000,-0.500000
CONTINUOUS	2.400000,3.400000,0.500000
COLOR	LINETYPE
YELLOW	SET
LINE	HIDDEN
2.400000,5.600000,-0.500000	COLOR
3.600000,5.600000,-0.500000	RED
Delay	LINE
500	2.400000,3.400000,0.500000
LINETYPE	3.000000,3.500000,0.500000
SET	LINETYPE
CONTINUOUS	SET
COLOR	CONTINUOUS
YELLOW	COLOR
LINE	YELLOW

LINE
3.000000,3.500000,0.500000
3.000000,3.500000,-0.500000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
3.000000,3.500000,-0.500000
3.000000,5.500000,-0.500000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
3.000000,5.500000,-0.500000
3.000000,5.500000,0.500000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
3.000000,5.500000,0.500000
7.000000,4.000000,0.500000

LINETYPE
SET
CONTINUOUS

COLOR

YELLOW
LINE
7.000000,4.000000,0.500000
7.000000,4.000000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
7.000000,4.000000,-0.800000
7.000000,4.000000,0.200000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
7.000000,4.000000,0.200000
9.000000,5.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
9.000000,5.000000,0.200000
9.000000,5.000000,-0.800000

Delay
500
LINETYPE
SET

CONTINUOUS

COLOR
YELLOW
LINE

9.000000,5.000000,-0.800000
9.000000,5.000000,0.200000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
9.000000,5.000000,0.200000
9.000000,3.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
9.000000,3.000000,0.200000
9.000000,3.000000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
9.000000,3.000000,-0.800000
9.000000,3.000000,0.200000

Delay

500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
9.000000,3.000000,0.200000
0.000000,0.000000,0.200000

APPENDIX D

THE SCRIPT FILE FOR FIGURE 5.2

LINETYPE	COLOR
SET	RED
HIDDEN	LINE
	8.000000,14.000000,-2.000000
	8.000000,14.000000,2.000000
COLOR	
RED	
LINE	LINETYPE
50.000000,50.000000,50.000000	SET
3.000000,14.000000,2.000000	HIDDEN
LINETYPE	COLOR
SET	RED
CONTINUOUS	LINE
	8.000000,14.000000,2.000000
	5.000000,14.000000,2.000000
COLOR	
YELLOW	
LINE	LINETYPE
3.000000,14.000000,2.000000	SET
3.000000,14.000000,-2.000000	CONTINUOUS
Delay	COLOR
500	YELLOW
LINETYPE	LINE
SET	5.000000,14.000000,2.000000
CONTINUOUS	5.000000,14.000000,-2.000000
COLOR	Delay
YELLOW	500
LINE	LINETYPE
3.000000,14.000000,-2.000000	SET
8.000000,14.000000,-2.000000	CONTINUOUS
Delay	COLOR
500	YELLOW
LINETYPE	LINE
SET	5.000000,14.000000,-2.000000
HIDDEN	5.000000,6.000000,-2.000000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
5.000000,6.000000,-2.000000
5.000000,6.000000,2.000000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
5.000000,6.000000,2.000000
11.000000,6.000000,2.000000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
11.000000,6.000000,2.000000
11.000000,6.000000,-2.000000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
11.000000,6.000000,-2.000000
16.000000,6.000000,-2.000000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
16.000000,6.000000,-2.000000
16.000000,6.000000,2.000000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
16.000000,6.000000,2.000000
11.000000,6.000000,2.000000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
11.000000,6.000000,2.000000
11.000000,6.000000,-2.000000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
11.000000,6.000000,-2.000000
11.000000,14.000000,-2.000000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
11.000000,14.000000,-2.000000
16.000000,14.000000,-2.000000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
16.000000,14.000000,-2.000000
16.000000,14.000000,2.000000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
16.000000,14.000000,2.000000
11.000000,10.000000,2.000000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
11.000000,10.000000,2.000000
11.000000,10.000000,-2.000000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
11.000000,10.000000,-2.000000
15.000000,10.000000,-2.000000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
15.000000,10.000000,-2.000000
15.000000,10.000000,2.000000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
15.000000,10.000000,2.000000
24.000000,12.000000,2.000000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
24.000000,12.000000,2.000000
24.000000,12.000000,-2.000000

Delay	LINETYPE
500	SET
Delay	CONTINUOUS
500	
LINETYPE	COLOR
SET	YELLOW
CONTINUOUS	ARC
	C
COLOR	22.000000,8.000000,-2.000000
YELLOW	20.000000,8.000000
ARC	22.000000,6.000000
C	Delay
22.000000,12.000000,-2.000000	500
24.000000,12.000000	LINETYPE
22.000000,14.000000	SET
Delay	CONTINUOUS
500	
LINETYPE	COLOR
SET	YELLOW
CONTINUOUS	ARC
	C
COLOR	22.000000,8.000000,-2.000000
YELLOW	22.000000,6.000000
ARC	24.000000,8.000000
C	LINETYPE
22.000000,12.000000,-2.000000	SET
22.000000,14.000000	HIDDEN
20.000000,12.000000	
Delay	COLOR
500	RED
LINETYPE	LINE
SET	24.000000,8.000000,-2.000000
CONTINUOUS	24.000000,8.000000,2.000000
COLOR	LINETYPE
YELLOW	SET
ARC	HIDDEN
C	
30.000000,10.000000,-2.000000	COLOR
20.000000,12.000000	RED
20.000000,8.000000	LINE
Delay	24.000000,8.000000,2.000000
500	27.000000,14.000000,2.000000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
27.000000,14.000000,2.000000
27.000000,14.000000,-2.000000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
27.000000,14.000000,-2.000000
27.000000,6.000000,-2.000000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
27.000000,6.000000,-2.000000
27.000000,6.000000,2.000000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
27.000000,6.000000,2.000000
32.000000,14.000000,2.000000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
32.000000,14.000000,2.000000
32.000000,14.000000,-2.000000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
32.000000,14.000000,-2.000000
32.000000,6.000000,-2.000000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
32.000000,6.000000,-2.000000
32.000000,6.000000,2.000000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
32.000000,6.000000,2.000000
27.000000,10.000000,2.000000

LINETYPE

SET
CONTINUOUS

COLOR
YELLOW
LINE

27.000000,10.000000,2.000000
27.000000,10.000000,-2.000000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
27.000000,10.000000,-2.000000
32.000000,10.000000,-2.000000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
32.000000,10.000000,-2.000000
32.000000,10.000000,2.000000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
32.000000,10.000000,2.000000
0.000000,0.000000,2.000000

APPENDIX E

THE SCRIPT FILE FOR FIGURE 5.3.

LINETYPE	LINE
SET	0.000000,4.250000,-0.800000
HIDDEN	-0.750000,4.250000,-0.800000
COLOR	Delay
RED	500
LINE	LINETYPE
5.000000,5.000000,0.500000	SET
0.000000,0.000000,0.200000	CONTINUOUS
LINETYPE	COLOR
SET	YELLOW
HIDDEN	LINE
	-0.750000,4.250000,-0.800000
COLOR	-0.750000,2.250000,-0.800000
RED	
LINE	Delay
0.000000,0.000000,0.200000	500
0.000000,4.250000,0.200000	LINETYPE
	SET
LINETYPE	CONTINUOUS
SET	
CONTINUOUS	COLOR
	YELLOW
COLOR	LINE
YELLOW	-0.750000,2.250000,-0.800000
LINE	0.000000,2.250000,-0.800000
0.000000,4.250000,0.200000	
0.000000,4.250000,-0.800000	Delay
	500
Delay	LINETYPE
500	SET
LINETYPE	HIDDEN
SET	
CONTINUOUS	COLOR
	RED
COLOR	LINE
YELLOW	0.000000,2.250000,-0.800000

0.000000,2.250000,0.200000

LINETYPE

SET

HIDDEN

COLOR

RED

LINE

0.000000,2.250000,0.200000

-0.500000,2.250000,0.200000

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

LINE

-0.500000,2.250000,0.200000

-0.500000,2.250000,-0.800000

Delay

500

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

LINE

-0.500000,2.250000,-0.800000

-0.500000,2.000000,-0.800000

Delay

500

LINETYPE

SET

HIDDEN

COLOR

RED

LINE

-0.500000,2.000000,-0.800000

-0.500000,2.000000,0.200000

LINETYPE

SET

HIDDEN

COLOR

RED

LINE

-0.500000,2.000000,0.200000

0.000000,2.000000,0.200000

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

LINE

0.000000,2.000000,0.200000

0.000000,2.000000,-0.800000

Delay

500

LINETYPE

SET

CONTINUOUS

COLOR

YELLOW

LINE

0.000000,2.000000,-0.800000

-1.000000,2.000000,-0.800000

Delay

500

Delay

500

LINETYPE

SET

CONTINUOUS

COLOR
YELLOW
ARC
C
-2.000000,2.000000,-0.800000
-2.000000,1.000000
-1.000000,2.000000
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.000000,1.000000,-0.800000
-2.000000,0.000000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-2.000000,0.000000,-0.800000
-2.000000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-2.000000,0.000000,0.200000
-2.000000,0.250000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.000000,0.250000,0.200000
-2.000000,0.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.000000,0.250000,-0.800000
-2.250000,0.250000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-2.250000,0.250000,-0.800000
-2.250000,0.250000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-2.250000,0.250000,0.200000
-2.250000,0.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.250000,0.000000,0.200000
-2.250000,0.000000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.250000,0.000000,-0.800000
-2.250000,0.500000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.250000,0.500000,-0.800000
-5.250000,0.500000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-5.250000,0.500000,-0.800000
-5.250000,0.000000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-5.250000,0.000000,-0.800000
-5.250000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-5.250000,0.000000,0.200000
-1.000000,0.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-1.000000,0.000000,0.200000
-1.000000,0.000000,-0.800000

Delay
500
Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC

C
0.000000,0.000000,-0.800000
0.000000,1.000000
-1.000000,0.000000
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,1.000000,-0.800000
0.000000,1.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,1.000000,0.200000
0.000000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,0.000000,0.200000
0.000000,4.250000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,4.250000,0.200000
0.000000,4.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,4.250000,-0.800000
0.750000,4.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.750000,4.250000,-0.800000
0.750000,2.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.750000,2.250000,-0.800000
0.000000,2.250000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,2.250000,-0.800000
0.000000,2.250000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,2.250000,0.200000
0.500000,2.250000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.500000,2.250000,0.200000
0.500000,2.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.500000,2.250000,-0.800000
0.500000,2.000000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.500000,2.000000,-0.800000
0.500000,2.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.500000,2.000000,0.200000
0.000000,2.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,2.000000,0.200000
0.000000,2.000000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,2.000000,-0.800000
1.000000,2.000000,-0.800000

Delay
500
Delay
500

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
2.000000,2.000000,-0.800000
1.000000,2.000000
2.000000,1.000000
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
2.000000,1.000000,-0.800000
2.000000,0.000000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
2.000000,0.000000,-0.800000
2.000000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
2.000000,0.000000,0.200000
2.000000,0.250000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
2.000000,0.250000,0.200000
2.000000,0.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
2.000000,0.250000,-0.800000
2.250000,0.250000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
2.250000,0.250000,-0.800000
2.250000,0.250000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
2.250000,0.250000,0.200000
2.250000,0.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
2.250000,0.000000,0.200000
2.250000,0.000000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
2.250000,0.000000,-0.800000
2.250000,0.500000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
2.250000,0.500000,-0.800000
5.250000,0.500000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW

LINE
5.250000,0.500000,-0.800000
5.250000,0.000000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
5.250000,0.000000,-0.800000
5.250000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
5.250000,0.000000,0.200000
1.000000,0.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
1.000000,0.000000,0.200000
1.000000,0.000000,-0.800000

Delay
500
Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
0.000000,0.000000,-0.800000
1.000000,0.000000
0.000000,1.000000
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,1.000000,-0.800000
0.000000,1.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,1.000000,0.200000
0.000000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,0.000000,0.200000
0.000000,-4.250000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR

YELLOW
LINE
0.000000,-4.250000,0.200000
0.000000,-4.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,-4.250000,-0.800000
-0.750000,-4.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-0.750000,-4.250000,-0.800000
-0.750000,-2.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-0.750000,-2.250000,-0.800000
0.000000,-2.250000,-0.800000

Delay
500

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,-2.250000,-0.800000
0.000000,-2.250000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,-2.250000,0.200000
-0.500000,-2.250000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-0.500000,-2.250000,0.200000
-0.500000,-2.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-0.500000,-2.250000,-0.800000
-0.500000,-2.000000,-0.800000

Delay

500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-0.500000,-2.000000,-0.800000
-0.500000,-2.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-0.500000,-2.000000,0.200000
0.000000,-2.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,-2.000000,0.200000
0.000000,-2.000000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,-2.000000,-0.800000
-1.000000,-2.000000,-0.800000

Delay
500
Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
-2.000000,-2.000000,-0.800000
-1.000000,-2.000000
-2.000000,-1.000000
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.000000,-1.000000,-0.800000
-2.000000,0.000000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-2.000000,0.000000,-0.800000
-2.000000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED

LINE
-2.000000,0.000000,0.200000
-2.000000,-0.250000,0.200000
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.000000,-0.250000,0.200000
-2.000000,-0.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
-2.000000,-0.250000,-0.800000
-2.250000,-0.250000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
-2.250000,-0.250000,-0.800000
-2.250000,-0.250000,0.200000

LINETYPE
SET
HIDDEN

COLOR

RED
 LINE
 -2.250000,-0.250000,0.200000
 -2.250000,0.000000,0.200000

 LINETYPE
 SET
 CONTINUOUS

 COLOR
 YELLOW
 LINE
 -2.250000,0.000000,0.200000
 -2.250000,0.000000,-0.800000

 Delay
 500
 LINETYPE
 SET
 CONTINUOUS

 COLOR
 YELLOW
 LINE
 -2.250000,0.000000,-0.800000
 -2.250000,-0.500000,-0.800000

 Delay
 500
 LINETYPE
 SET
 CONTINUOUS

 COLOR
 YELLOW
 LINE
 -2.250000,-0.500000,-0.800000
 -5.250000,-0.500000,-0.800000

 Delay
 500
 LINETYPE
 SET

CONTINUOUS

 COLOR
 YELLOW
 LINE
 -5.250000,-0.500000,-0.800000
 -5.250000,0.000000,-0.800000

 Delay
 500
 LINETYPE
 SET
 HIDDEN

 COLOR
 RED
 LINE
 -5.250000,0.000000,-0.800000
 -5.250000,0.000000,0.200000

 LINETYPE
 SET
 HIDDEN

 COLOR
 RED
 LINE
 -5.250000,0.000000,0.200000
 -1.000000,0.000000,0.200000

 LINETYPE
 SET
 CONTINUOUS

 COLOR
 YELLOW
 LINE
 -1.000000,0.000000,0.200000
 -1.000000,0.000000,-0.800000

 Delay
 500
 Delay

500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
ARC
C
0.000000,0.000000,-0.800000
-1.000000,0.000000
0.000000,-1.000000
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,-1.000000,-0.800000
0.000000,-1.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,-1.000000,0.200000
0.000000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,0.000000,0.200000
0.000000,-4.250000,0.200000

LINETYPE

SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,-4.250000,0.200000
0.000000,-4.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,-4.250000,-0.800000
0.750000,-4.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.750000,-4.250000,-0.800000
0.750000,-2.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.750000,-2.250000,-0.800000

0.000000,-2.250000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,-2.250000,-0.800000
0.000000,-2.250000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.000000,-2.250000,0.200000
0.500000,-2.250000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.500000,-2.250000,0.200000
0.500000,-2.250000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE

0.500000,-2.250000,-0.800000
0.500000,-2.000000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.500000,-2.000000,-0.800000
0.500000,-2.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
0.500000,-2.000000,0.200000
0.000000,-2.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
0.000000,-2.000000,0.200000
0.000000,-2.000000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW

LINE
 0.000000,-2.000000,-0.800000
 1.000000,-2.000000,-0.800000

 Delay
 500
 Delay
 500
 LINETYPE
 SET
 CONTINUOUS

 COLOR
 YELLOW
 ARC
 C
 2.000000,-2.000000,-0.800000
 2.000000,-1.000000
 1.000000,-2.000000
 LINETYPE
 SET
 CONTINUOUS

 COLOR
 YELLOW
 LINE
 2.000000,-1.000000,-0.800000
 2.000000,0.000000,-0.800000

 Delay
 500
 LINETYPE
 SET
 HIDDEN

 COLOR
 RED
 LINE
 2.000000,0.000000,-0.800000
 2.000000,0.000000,0.200000

 LINETYPE
 SET

HIDDEN

 COLOR
 RED
 LINE
 2.000000,0.000000,0.200000
 2.000000,-0.250000,0.200000

 LINETYPE
 SET
 CONTINUOUS

 COLOR
 YELLOW
 LINE
 2.000000,-0.250000,0.200000
 2.000000,-0.250000,-0.800000

 Delay
 500
 LINETYPE
 SET
 CONTINUOUS

 COLOR
 YELLOW
 LINE
 2.000000,-0.250000,-0.800000
 2.250000,-0.250000,-0.800000

 Delay
 500
 LINETYPE
 SET
 HIDDEN

 COLOR
 RED
 LINE
 2.250000,-0.250000,-0.800000
 2.250000,-0.250000,0.200000

 LINETYPE

SET
HIDDEN

COLOR
RED
LINE

2.250000,-0.250000,0.200000
2.250000,0.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE

2.250000,0.000000,0.200000
2.250000,0.000000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE

2.250000,0.000000,-0.800000
2.250000,-0.500000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE

2.250000,-0.500000,-0.800000
5.250000,-0.500000,-0.800000

Delay
500
LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
5.250000,-0.500000,-0.800000
5.250000,0.000000,-0.800000

Delay
500
LINETYPE
SET
HIDDEN

COLOR
RED
LINE
5.250000,0.000000,-0.800000
5.250000,0.000000,0.200000

LINETYPE
SET
HIDDEN

COLOR
RED
LINE
5.250000,0.000000,0.200000
1.000000,0.000000,0.200000

LINETYPE
SET
CONTINUOUS

COLOR
YELLOW
LINE
1.000000,0.000000,0.200000
1.000000,0.000000,-0.800000

	0.000000,0.000000,0.200000
Delay	6.000000,5.000000,0.200000
500	
Delay	
500	
LINETYPE	
SET	
CONTINUOUS	
COLOR	
YELLOW	
ARC	
C	
0.000000,0.000000,-0.800000	
0.000000,-1.000000	
1.000000,0.000000	
LINETYPE	
SET	
HIDDEN	
COLOR	
RED	
LINE	
0.000000,-1.000000,-0.800000	
0.000000,-1.000000,0.200000	
LINETYPE	
SET	
HIDDEN	
COLOR	
RED	
LINE	
0.000000,-1.000000,0.200000	
0.000000,0.000000,0.200000	
LINETYPE	
SET	
HIDDEN	
COLOR	
RED	
LINE	

APPENDIX F

USER MANUAL

The following steps show users how to use this NC tool path simulation software in AutoCAD.

F.1 Adding an External Command to the acad.pgp File

1. Before making changes to the *acad.pgp* file, make a backup of the file and save it under an other name. This ensures that if the changes of the *acad.pgp* file get some errors, the original copy still can be used.
2. To use text editor of the DOS operating system from inside AutoCAD, start edit the *acad.pgp* file and save it.

C:\> *cd acad*

C:\acad>*acadr12* (open the AutoCAD)

Command: *shell*

OS Command: *edit c:\acad\support\acad.pgp*

3. Add the line “*TRIAC,TRIAC, 0,4*”.
4. Save the modified *acad.pgp* file in ASCII format and quit the text editor.
5. Start AutoCAD, and check the *acad.pgp* file is located in the correct directory.

Command: *edit*

File to Modify: *c:\acad\support\acad.pgp*

The text editor should start with the *acad.pgp* file. If there is any error message, and the file is in a different directory, check the entered the external command correctly in *acad.pgp*, or change to the correct directory.

F.2 Creating a New Command by Using AutoLISP Language

- To use text editor of the DOS operating system from inside AutoCAD, start edit the *STOCK.LSP* file and save it.

C:\> *cd acad*

C:\acad>*acadrl2* (open the AutoCAD)

Command: *shell*

OS Command: *edit stock.lsp*

STOCK.LSP

```
(setq width 100)
```

```
(setq height 20)
```

```
(setq length 150)
```

```
(defun C: stock(/ len wid hei)
```

```
  (princ "\nEnter the New Stock Length<" )(princ length)(princ ">:")
```

```
    (setq len (getint))
```

```
    (if len
```

```
      (setq length len)
```

```
    )
```

```
(princ "\nEnter the New Stock Width <")(princ width)(princ ">:")
```

```
  (setq wid (getint))
```

```
  ( if wid
```

```
    (setq width wid)
```

```
  )
```

```
(princ "\nEnter the New Stock Height<")(princ height)(princ ">:")
```

```
  (setq hei (getint))
```

```
  (if hei
```

```
    (setq height hei)
```

```
  )
```

```
(command "erase" "l" "")
```



```

(command "color" "green")
(command "pline" "0,0" (list length 0)(list length width)(list 0
width)"c")
(command "change" "l" "" "p" "t" height "el" (-height)""")
)

```

F.3 Install C Program

Install C program TRIAC.EXE as follow.

C:\> ***cd acad***

C:\ACAD> ***copy triac.exe a:***

F.4 Using Script Command to Generate NC Tool Path

1. Enter AutoCAD.

C:\ACAD> ***acadrl2***

2. Open the drawing file TRIAC.DWG.

Command: ***open***, and pick "***triac.dwg***" from AutoCAD dialogue box.

3. Control stock size by using STOCK command.

Command: (***load "stock.lsp"***)

Command: ***stock***

- Enter New Stock Length <120>:
- Enter New Stock Width <100>:
- Enter New Stock Height <15>:
- Use TRIAC command to check errors for NC code and transfer it to a "***Script***" file.

Command: ***triac***

Enter NC code Filename: *code.NC*

Script Filename: *code.SCR*

4. Simulate the tool path by using **SCRIPT** command.

Command: *script*

Script filename: *code.scr*

- Red Dashed-lines indicate G00-- Rapid movement of tool.
- Yellow Continuous lines indicate G01, G02 or G03 -- Variable feed movement of tool.

5. Quit AutoCAD by using Command: *QUIT* without saving the drawing.